

DEVELOPMENT OF UNIVARIATE CONTROL CHARTS FOR NON-NORMAL DATA

**A Thesis Submitted to the
Graduate School of Engineering and Sciences of
İzmir Institute of Technology
In Partial Fullfilment of the Requirements for the Degree of
MASTER OF SCIENCE
in Materials Science and Engineering**

**By
Cihan ÇİFLİKLİ**

December 2006

İZMİR

We approve the thesis of **Cihan ÇİFLİKLİ**

Date of Signature

.....
Assist. Prof. Dr. Fuat DOYMAZ
Supervisor
Department of Chemical Engineering
İzmir Institute of Technology

4 December 2006

.....
Assoc. Prof. Dr. Sedat AKKURT
Co-Supervisor
Department of Materials Science and Engineering
İzmir Institute of Technology

4 December 2006

.....
Prof. Dr. Halis PÜSKÜLCÜ
Department of Computer Engineering
İzmir Institute of Technology

4 December 2006

.....
Prof. Dr. Mehmet POLAT
Department of Chemical Engineering
İzmir Institute of Technology

4 December 2006

.....
Assist. Prof. Dr. Mustafa ALTINKAYA
Department of Electrical and Electronics Engineering
İzmir Institute of Technology

4 December 2006

.....
Prof. Dr. Muhsin ÇİFTÇİOĞLU
Head of Department of Materials Science and Engineering
İzmir Institute of Technology

4 December 2006

.....
Head of the Graduate School

ACKNOWLEDGEMENT

I would like to express my sincere gratitude to my advisor Assist. Prof. Dr. Fuat Doymaz and co-advisor Assoc. Prof. Dr. Sedat Akkurt for their supervision, guidance and generosity in sharing their expertise.

I would like to appreciate Prof. Dr. Muhsin iftioęlu, Prof. Dr. Halis Puskülcü, Prof. Dr. Mehmet Polat, Assist.Prof. Dr. Mustafa Altinkaya and Assist.Prof. Dr. Figen Tokatlı for their understanding, support and encouragement.

I am thankful to imentaş A.Ş. and Burak Akyol for their support.

Special thanks to Levent Aydın, İlker Polatoęlu, Hakkı Erhan Sevil, Filiz Yaşar and all my friends for their friendship, help and understanding.

Finally, I want to express my gratitude to my family who made it possible to overcome all the obstacles I have come across throughout this work.

ABSTRACT

DEVELOPMENT OF UNIVARIATE CONTROL CHARTS FOR NON-NORMAL DATA

In this study, a new control chart methodology was developed to address statistical process monitoring issue associated with non-normally distributed process variables. The new method (NM) was compared against the classical Shewhart control chart (OM) using synthetic datasets from normal and non-normal distributions as well as over an industrial example. The NM involved taking the difference between the specified probability density estimate and non-parametric density estimate of the variable of interest to calculate an error value. Both OM and NM were found to work well for normally distributed data when process is in-control and out-of control situation. Both methods could be returned back to normal operation upon feeding in-control data.

In case of non-normally distributed data, the OM failed significantly to detect small shifts in mean and standard deviation, however the NM maintained its performance to detect such changes.

In the application to an industrial case (data were obtained from a local cement manufacturer about a 90 micrometer sieve fraction of the final milled cement product), the NM methodology outperformed the OM by recognizing the change in the mean and variance of the measured parameter. The data were tested for its distribution and were found to be non-normally distributed. Violations beyond the control limits in the new developed technique were easily observed. The NM was found to successfully operate without the necessity to apply run rules.

ÖZET

NORMAL DAĞILIMA SAHİP OLMAYAN DEĞİŞKENLER İÇİN KONTROL GRAFİKLERİNİN GELİŞTİRİLMESİ

Bu çalışmada, normal olarak dağılmayan proses değişkenleri ile ilintili istatistiksel proses gözleme amacına cevap verecek yeni bir kontrol grafiği metodolojisi geliştirilmiştir. Rastgele normal, normal olmayan dağılımlara sahip olan ve sanayi veri kümelerine Shewhart kontrol grafiklerinin (EY) uygulanması ve bunların yeni yöntem (YY) ile kıyaslanması yapılmıştır. YY bir hata değeri hesaplamak için, ilgili değişkenin parametrik olmayan yoğunluk tahmini değerinin ve belirlenen ihtimal yoğunluğu tahmininin arasındaki farkın bulunmasını kapsar. Normal dağılmış verinin kontrol altında ve kontrol dışındaki durumları için EY ve YY yöntemlerinin her ikisinin de iyi çalıştığı gözlemlendi. Kontrol sınırları içinde veri beslenince her iki yöntemin de normal operasyona döndürülebildiği gösterildi.

Normal dağılmayan veri durumunda ise, EY ortalama ve standard sapmadaki küçük değişiklikleri yakalamada başarısız olurken YY bu değişiklikleri yakalamada başarılı oldu.

YY'in çimento üreticisinden temin edilen ve 90 mikron elek üstü öğütülmüş çimento miktarını (DACK 90) içeren sanayi verilerine uygulanması durumunda EY'e göre ölçülen parametrenin ortalaması ve varyansındaki değişiklikleri tanımada daha başarılı olduğu tespit edildi. Verinin dağılımı sınırdı ve normal olmayan şekilde dağıldığı tespit edildi. YY'ta kontrol sınırları dışında kalan ihlaller kolaylıkla gözlemlendi. YY'un, çalışma kurallarına gerek duymadan, başarıyla uygulanabildiği görüldü.

TABLE OF CONTENTS

| | |
|--|------|
| LIST OF FIGURES | viii |
| LIST OF TABLES..... | xi |
| GLOSSARY OF ABBREVIATIONS | xii |
| CHAPTER 1. INTRODUCTION..... | 1 |
| CHAPTER 2. LITERATURE SURVEY | 3 |
| 2.1. Statistical Process Control..... | 3 |
| 2.2. Control Charts | 4 |
| 2.2.1. Control Charts for Normal Data | 6 |
| 2.2.1.1. Shewhart Control Chart | 6 |
| 2.2.1.2. Calculation of ARL and ATS | 7 |
| 2.2.1.3. Statistically Designed Control Charts..... | 8 |
| 2.2.2. Control Charts for Non-normal Data | 8 |
| 2.2.2.1. Burr Distribution..... | 8 |
| 2.2.2.2. The Variable Sampling Interval (VSI) \bar{X} Control Chart..... | 10 |
| CHAPTER 3. THE PROPOSED METHOD AND THE MODEL..... | 11 |
| 3.1. The Data | 11 |
| 3.1.1. Normally Distributed Random Data | 11 |
| 3.1.2. Non-normally Distributed Random Data | 11 |
| 3.1.3. Industrial Data | 13 |
| 3.2. Proposed Methodology | 15 |
| 3.2.1. The Shewhart Method (OM)..... | 15 |
| 3.2.2. The New Method (NM)..... | 16 |
| 3.3. Functions Used in Matlab | 18 |
| 3.3.1. Normrnd (Random Matrices from Normal Distribution)..... | 18 |
| 3.3.2. Normpdf and Chi2pdf | 18 |
| 3.3.3. Kernel Density Estimators (Ksdensity)..... | 19 |

| | |
|--|----|
| 3.3.4. Normal Cumulative Distribution Function (normcdf) and Chi-square Cumulative Distribution Function (chi2cdf)..... | 20 |
| 3.3.4.1. Normal Cumulative Distribution Function (Normcdf)..... | 21 |
| 3.3.4.2. Chi-square Cumulative Distribution Function (chi2cdf)..... | 22 |
| | |
| CHAPTER 4. RESULTS AND DISCUSSION | 23 |
| 4.1. Results of OM and NM for Normally Distributed Data..... | 23 |
| 4.1.1. Application of OM for 0.01 α | 24 |
| 4.1.2. Application of NM for 0.01 α | 30 |
| 4.2. Results of OM and NM for Non-normally Distributed Data | 36 |
| 4.2.1. Application of OM for 0.01 α | 36 |
| 4.2.2. Application of NM for 0.01 α | 40 |
| 4.3. Results of OM and NM for Industrial Data..... | 44 |
| 4.3.1. Application of OM for 0.01 α | 44 |
| 4.3.2. Application of NM for 0.01 α | 46 |
| | |
| CHAPTER 5. CONCLUSIONS AND RECOMMENDATIONS FOR FUTURE STUDY | 48 |
| | |
| REFERENCES | 50 |
| | |
| APPENDICES | |
| APPENDIX A..... | 52 |
| APPENDIX B | 56 |
| APPENDIX C | 59 |
| APPENDIX D..... | 61 |

LIST OF FIGURES

| <u>Figure</u> | <u>Page</u> |
|--|--------------------|
| Figure 2.1. Structure of a control chart | 5 |
| Figure 3.1. Histogram of the normally distributed data used in this study (NDNOD) | 12 |
| Figure 3.2. Histogram of the non- normally distributed data used in this study (NNDNOD)3..... | 12 |
| Figure 3.3. Complete industrial data used in this study. | 14 |
| Figure 3.4. Histogram for normal operation part (950 data points) of industrial data..... | 14 |
| Figure 3.5. Check for normality of the ND part (950 data points) of the ID. | 15 |
| Figure 3.6. Plots of ksdensity and normal probability density function (normpdf) Wavy line indicates the ksdensity estimate while the other smooth line shows pdf | 17 |
| Figure 3.7. Plots of ksdensity and chi-square probability density function (chi2pdf).Wavy line indicates the ksdensity estimate while the other smooth line shows pdf | 17 |
| Figure 3.8. Visualization of the probability density function | 18 |
| Figure 4.1. Shewhart control chart for normally distributed random data..... | 25 |
| Figure 4.2. Shewhart control chart for normally distributed random data after its mean is shifted by 0.1 unit. | 25 |
| Figure 4.3. Shewhart control chart for normally distributed random data after its mean is shifted by 0.25 unit..... | 26 |
| Figure 4.4. Shewhart control chart for normally distributed random data after its mean is shifted by 0.5 unit..... | 26 |
| Figure 4.5. Shewhart control chart for normally distributed random data after its mean is shifted by 1 unit | 27 |
| Figure 4.6. Shewhart control chart for normally distributed random data after its std is increased by 0.1 unit. The new standard deviation is 1.1 | 27 |
| Figure 4.7. Shewhart control chart for normally distributed random data after its std is increased by 0.25 unit. The new standard deviation is 1.25 | 28 |

| | |
|--|----|
| Figure 4.8. Shewhart control chart for normally distributed random data after its std is increased by 0.5 unit. The new standard deviation is 1.5 | 28 |
| Figure 4.9. Shewhart control chart for normally distributed random data after its mean is shifted by 1 unit. The new standard deviation is 2 | 29 |
| Figure 4.10. Shewhart control chart for normally distributed random data after the data is modified to return it back to normal operation..... | 29 |
| Figure 4.11. Error control chart for NM for normally distributed random data when the operation is in-control | 30 |
| Figure 4.12. Error chart for normally distributed data after its mean is shifted by 0.1 unit | 31 |
| Figure 4.13. Error chart for normally distributed data after its mean is shifted by 0.25 unit | 31 |
| Figure 4.14. Error chart for normally distributed data after its mean is shifted by 0.5 unit | 32 |
| Figure 4.15. Error chart for normally distributed data after its mean is shifted by 1 unit | 32 |
| Figure 4.16. Error chart for normally distributed data after its std is increased by 0.1 unit. The new standard deviation is 1.1 | 33 |
| Figure 4.17. Error chart for normally distributed data after its std is increased by 0.25 unit. The new standard deviation is 1.25 | 33 |
| Figure 4.18. Error chart for normally distributed data after its std is increased by 0.5 unit. The new standard deviation is 1.5 | 34 |
| Figure 4.19. Error chart for normally distributed data after its std is increased by 1 unit. The new standard deviation is 2 | 34 |
| Figure 4.20. Plots of ksdensity and normal probability density function (normpdf) after the data is modified to return it back to normal operation Wavy line indicates the ksdensity estimate while the other smooth line shows pdf..... | 35 |
| Figure 4.21. Error control chart for normally distributed random data after the data is modified to return it back to normal operation..... | 35 |
| Figure 4.22. Shewhart control chart for non-normally distributed random data for in-control situation | 37 |
| Figure 4.23. Shewhart control chart for non-normally distributed random data after it is shifted by 0.1 unit | 37 |

| | |
|--|----|
| Figure 4.24. Shewhart control chart for non-normally distributed random data after it is shifted by 0.25 unit | 38 |
| Figure 4.25. Shewhart control chart for non-normally distributed random data after it is shifted by 0.5 unit | 38 |
| Figure 4.26. Shewhart control chart for non-normally distributed random data after it is shifted by 1 unit | 39 |
| Figure 4.27. Shewhart control chart for non-normally distributed random data after the data is modified to return it back to normal operation | 39 |
| Figure 4.28. Error chart for chi-square distributed data (NNDD) for in-control situation | 40 |
| Figure 4.29. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.1 unit | 41 |
| Figure 4.30. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.25 unit | 41 |
| Figure 4.31. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.5 unit. | 42 |
| Figure 4.32. Error chart for chi-square distributed data (NNDD) after it is shifted by 1 unit | 42 |
| Figure 4.33. Plots of ksdensity and chi-square probability density function (chi2pdf) after the process is returned back to in-control situation. Wavy line indicates the ksdensity estimate while the other smooth line shows pdf..... | 43 |
| Figure 4.34. Error chart for chi-square distributed data (NNDD) after the process is returned back to in-control situation. | 43 |
| Figure 4.35. Shewhart control chart for industrial data for normal operation | 45 |
| Figure 4.36. Shewhart control chart for industrial data for out-of-control situation..... | 45 |
| Figure 4.37. Plots of ksdensity and normpdf for industrial data for the in-control situation. Dark continuous line shows ksdensity values while the dots show pdf values | 46 |
| Figure 4.38. Error chart for industrial data for normal operation | 47 |
| Figure 4.39. Error chart for industrial data for out-of control situation..... | 47 |

LIST OF TABLES

| <u>Table</u> | | <u>Page</u> |
|---------------------|--|--------------------|
| Table 4.1. | List of the figures which show the progression of error charts in this study | 24 |

GLOSSARY OF ABBREVIATIONS

| | |
|------------------|---|
| OM | Old Method or the Shewhart Control Chart Method |
| NM | New Method That is Developed in This Thesis |
| NDD | Normally Distributed Data |
| NNDD | Non-normally Distributed Data |
| NND-ID | Non-normally Distributed Industrial Data |
| ATS | Average Time to Signal |
| ARL | Average Run Length |
| NNDNOD | Non-normally Distributed Normal Operation Data |
| NDNOD | Normally Distributed Normal Operation Data |
| EWMA | Exponentially Weighted Moving Average |
| CUSUM | Cumulative Sum |
| CC | Control Chart |
| UCL | Upper Control Limit |
| LCL | Lower Control Limit |
| SPC | Statistical Process Control |
| UWL | Upper Warning Limit |
| LWL | Lower Warning Limit |
| VSI | Variable Sampling Interval |
| ID | Industrial Data |
| CPCT | Cumulative Percent Coarser Than |
| ND | Normally Distributed |
| RF | Relative Frequency |
| KSDENSITY | Kernel Smoothing Density Estimation |
| NORMPDF | Normal Probability Density Function |
| NPDF | Normal Probability Density Function |
| CHI2PDF | Chi-square Probability Density Function |
| NORMRND | Random Matrices from Normal Distribution |
| KDE | Kernel Density Estimators |
| NORMCDF | Normal Cumulative Distribution Function |
| CHI2CDF | Non-normal Cumulative Distribution Function |
| STD | Standard Deviation |

CHAPTER 1

INTRODUCTION

The main work of SQC (Statistical Quality Control) is to control the central tendency and variability of some processes. A common monitoring tool is to construct control charts “(Dou and Ping 2002)”. A control chart (CC) is a statistical scheme (usually allowing graphical implementation) devised for the purpose of checking and then monitoring the statistical stability of a process.

An efficient CC must continue sampling as long as the process is in-control and must give an out-of control signal to stop sampling as quickly as possible when the process becomes out-of-control “(Bakir 2004)”. The major function of control charting is to detect the occurrence of assignable causes so that the necessary corrective action may be taken before a large quantity of non-conforming product is manufactured “(Chou et al. 2001)”. The most widely used method to control the central tendency of a process is Shewhart-X chart “(Shewhart 1931)” which includes a centerline and two control limit lines.

There are two other possible alternatives to the Shewhart control charts in the construction of the central location control charts. One is the CUSUM (Cumulative Sum) chart and the other is the EWMA (Exponentially Weighted Moving Average) chart. Both of these concentrate on improving the performance of control charts in detecting small shifts by using historical data “(Dou and Ping 2002)”.

Various control chart techniques have been developed and widely applied in process control. Duncan’s cost model “(Duncan 1956)” includes the cost of an out-of-control condition, the cost of false alarms, the cost of searching for an assignable cause, and the cost of sampling, inspection, evaluation, and plotting. In addition to the economic design of control charts, another approach to designing a control chart is called statistical design “(Chou et al. 2001)”.

In real industrial applications, the process populations are frequently not normally distributed. Burr discussed the effects of non-normality and provided appropriate control constants for different non-normal populations. All the distributions considered belong to the Burr family “(Burr 1967)”, which is of the following form:

$$F(y) = \begin{cases} 1 - (1 + y^c)^{-a}, & y \geq 0, \\ 0, & y < 0, \end{cases} \quad (1)$$

“(Yourstone and Zimmer 1992)” used the Burr distribution to represent various non-normal distributions and consequently to statistically design the control limits of an X control chart. “(Chou and Cheng 1997)” extended the model presented by Yourstone and Zimmer to design the control limits of the ranges control chart under non-normality. Also, “(Tsai 1990)” employed the Burr distribution to design the probabilistic tolerance for a subsystem. “(Rahim 1985)” proposed an economic model of the \bar{x} chart for non-normal data by transforming the standardized normal random variate to non-normal variates.

If the non-normal process distribution really should be non-normal, it is necessary to use new knowledge to manage and improve the process. One software package can even adjust the control limits and the center line of the control chart so that control charts for non-normal data are statistically equivalent to Shewhart control charts for normal data.

The aim of this study is to design the control chart for non-normal data. Firstly the error chart was developed by taking difference between the probability density function (pdf) and non-parametric density estimation (ksdensity) for the normal distribution. Upper control limit (UCL) and lower control limit (LCL) of the process were determined. Then this procedure was applied for chi-square which is one of the non-normal distributions and applied for industrial data.

The second chapter presents the principles of statistical process control and the work done in the literature on control charts. The data and the method used in this study is given in chapter three. Fourth chapter presents the results of the control charts developed in this study and their comparison to the Shewhart method. Finally, conclusions are given in the fifth chapter.

CHAPTER 2

LITERATURE SURVEY

2.1. Statistical Process Control

It is impossible to inspect or test quality into a product; the product must be built right the first time. This implies that the manufacturing process must be stable and that all individuals involved with the process (including operators, engineers, quality assurance personnel, and management) must continuously seek to improve process performance and reduce variability in key parameters. On-line statistical process control (SPC) is a primary tool for achieving this objective.

If a product is to meet or exceed customer expectations, generally it should be produced by a process that is stable or repeatable. More precisely, the process must be capable of operating with little variability around the target or nominal dimensions of the product's quality characteristics. SPC is a powerful collection of problem-solving tools useful in achieving process stability and improving capability through the reduction of variability.

SPC can be applied to *any* process. Its seven major tools are:

1. Histogram or stem-and-leaf plot
2. Check sheet
3. Pareto chart
4. Cause-and-effect diagram
5. Defect concentration diagram
6. Scatter diagram
7. Control chart

Although these tools, often called "the magnificent seven", are an important part of SPC, they comprise only its technical aspects. SPC builds an environment in which all individuals in an organization seek continuous improvement in quality and productivity. This environment is best developed when management becomes involved in the process. Once this environment is established, routine application of the

magnificent seven becomes part of the usual manner of doing business, and organization is well on its way to achieving its quality improvement objectives.

Control charts are the simplest type of on-line statistical process control procedure.

2.2. Control Charts

Control charts are useful for tracking process statistics over time and detecting the presence of special causes. A special cause results in variation that can be detected and controlled. Examples of special causes include supplier, shift, or day of the week differences. Common cause variation, on the other hand, is variation that is inherent in the process. A process is in control when only common causes - not special causes - affect the process output.

Variable control charts, described here, plot statistics from measurement data, such as length or pressure. Attributes control charts plot count data, such as the number of defects or defective units. For instance, products may be compared against a standard and classified as either being defective or not. Products may also be classified by their number of defects.

A process statistic, such as a subgroup mean, individual observation, or weighted statistic, is plotted versus sample number or time. As with variables control charts, a process statistic, such as the number of defects, is plotted versus sample number or time for attributes control charts. A “center line” is drawn at the average of the statistic being plotted for the time being charted. Two other lines - the upper and lower control limits - are drawn, by default, 3σ above and below the center line (Figure 2.1.)

A process is in control when most of the points fall within the bounds of the control limits, and the points do not display any nonrandom pattern.




Figure 2.1. Structure of a control chart

The number of sampling instances before the CC signals is called the run length, which we denote by L . The efficiency of a CC depends on the distribution of the run length L . The most common and simplest efficiency criterion is to consider the average run length (ARL), which is the expected value of the run length distribution. It is desirable that the ARL of a CC be large if the process is in-control and be small if the process is out-of-control “(Chou et al. 2004)”. The false alarm rate is the probability that the CC gives an out-of-control signal when in fact the process is in-control. Most control charts are distribution-based procedures in the sense that the observations made on the process output are assumed to follow a specified probability CCs. “(Amin et al. 1995)” found a pronounced difference in the values of the in-control ARL of the Shewhart \bar{X} -chart under various distributions. Assuming a known standard deviation and a sample size of $n=10$, they found the exact values of the in-control ARLs of the traditional (one-sided) $3\sigma\bar{x}$ Shewhart \bar{X} -chart to be: 1068.7 under a uniform distribution, 740.8 under a normal distribution, 441.9 under a double exponential distribution, and 11.7 under a Cauchy distribution. This implies that for heavy-tailed underlying distributions, false alarms will occur much more frequently than expected when the process is operating in-control. For example, when the process has a Cauchy distribution, the in-control ARL will only be 11.7, which entails almost 63 times as many false alarms as the anticipated ARL value of 740.8 associated with the traditional $3\sigma\bar{x}$ Shewhart control limits “(Bakir 2004)”.

Traditionally, when the issue on designing control chart is discussed, one usually assumes the measurements in each sampled subgroup (or say population) are normally distributed; therefore, the sample mean \bar{X} is also normally distributed “(Chou et al. 2004)”.

2.2.1. Control Charts for Normal Data

In this section control charts for normal data are explained. First Shewhart Control Charts are discussed followed by some introductory information about the ARL and ATS.

2.2.1.1. Shewhart Control Chart

Since 1924 when Dr. Shewhart presented the first control chart, various control chart techniques have been developed and widely applied as a primary tool in statistical process control. A survey by “(Saniga and Shirland 1977)” indicated that the control chart for averages (or the \bar{X} chart) dominates the use of any other control chart technique if quality is measured on a continuous scale “(Chou 2001)”.

When the \bar{X} control chart is used to monitor a process, three parameters should be determined: the sample size, the sampling interval between successive samples, and the control limits of the chart which are UCL (Upper Control Limit) and LCL (Lower Control Limit) “(Chou 2000)”:

$$UCL = \bar{X} + K\sigma\bar{X} \quad (2)$$

$$CL = \bar{X} \quad (3)$$

$$LCL = \bar{X} - K\sigma\bar{X} \quad (4)$$

where

$$\bar{X} = \frac{\bar{X}_1 + \bar{X}_2 + \dots + \bar{X}_m}{m} \quad (5)$$

is the grand average, K is the control constant and $\sigma_{\bar{X}}$ is the standard deviation of sample mean and m is the number of samples taken. There are tables available for values of K based on the sample sizes and process requirements “(Montgomery 2005)”. Shewhart also suggested 3-sigma control limits as action limits and sample sizes of four or five, leaving the interval between successive subgroups to be determined by the practitioner “(Chou 2001)”.

In process control using Shewhart Control Charts, common practice is to observe for data points that lie outside of the control limits during normal operation. When such data are collected there are criteria that are developed to determine whether the process is out of control. These are known as run-rules. Western Electric Handbook presents a comprehensive discussion of the issue “(Western Electric Handbook 1956)”.

2.2.1.2. Calculation of ARL and ATS

In-control average run length(ARL), out-of-control ARL and average time to signal were evaluated for $\alpha=0.01$. These values were computed by equation 6, 7 and 8 “(Montgomery 2005)”.

$$\text{In-control ARL} = ARL_0 = \frac{1}{\alpha} \quad (6)$$

$$\text{Out-of-control ARL} = ARL_1 = \frac{1}{1 - \beta} \quad (7)$$

$$ATS = ARL * h \quad (8)$$

$$\beta = \Phi \left[\frac{UCL - (\mu_0 + k\sigma)}{\sigma / \sqrt{n}} \right] - \Phi \left[\frac{LCL - (\mu_0 + k\sigma)}{\sigma / \sqrt{n}} \right] \quad (9)$$

where α is the probability of making type I error, β is the probability of making type II error, h is time, Φ is the cumulative distribution function and μ_0 is the mean in the in-control case.

2.2.1.3. Statistically Designed Control Charts

Statistically designed control charts are those in which control limits (which determine the Type I error probability, α) and power are preselected. These then determine the sample size and, if the average time to signal is specified, the sampling interval “(Woodall,1985)”. “(Saniga 1989)” incorporated the concept of statistical considerations into the economic design of the control charts and then presented the ‘economic statistical design’ of the joint X and R charts for normal data

2.2.2. Control Charts for Non-Normal Data

The normality assumption may not be tenable every time. For example, the distributions of measurements from chemical processes, semiconductor processes, or cutting tool wear process are often skewed “(Chang and Bai, 2001)”. If the measurements are really normally distributed, the statistic X, which is the sample characteristic of interest, is also normally distributed. If the measurements are asymmetrically distributed, the statistic X will be approximately normally distributed only when the sample size n is sufficiently large (based on the central limit theorem) and when its. Unfortunately, when a control chart is applied to monitor the process, the sample size n is always not sufficiently large due to the sampling cost. Therefore, if the measurements are not normally distributed, the traditional way for designing the control chart may reduce the ability that a control chart detects the assignable causes “(Chou 2001)”.

The non-normal behavior of measurements may imply that the traditional design approach is improper for the operation of control charts.

2.2.2.1. Burr Distribution

The Burr cumulative distribution function “(Burr, 1942)” is

$$F(y) = 1 - \frac{1}{(1 + y^c)^q}, \quad \text{for } y \geq 0, \quad (10)$$

where c and q are greater than 1. “(Burr 1967)” applied his distribution to study the effect of non-normality on the constants of X and R control charts. “(Burr 1942)” tabulated the expected value, standard deviation, skewness coefficient, and kurtosis coefficient of the Burr distribution for various combinations of c and q . These tables allow the users to make a standardized transformation between a Burr variate (say, Y) and another random variate (X)

Denote UCL , LCL , UWL , and LWL as the upper control limit, lower control limit, upper warning limit, and lower warning limit, respectively. Expressed mathematically, we obtain

$$UCL = \mu_0 + k\sigma / \sqrt{n}, \quad LCL = \mu_0 - k\sigma / \sqrt{n}, \quad (11)$$

$$UWL = \mu_0 + w\sigma / \sqrt{n}, \quad LWL = \mu_0 - w\sigma / \sqrt{n}, \quad (12)$$

where μ_0 is the process mean when the process is in control. In this article, to simplify the model, we assume that when the process is out of control, the process mean shifts to $\mu_1 = \mu_0 + \delta\sigma$, but the process standard deviation remains unchanged. The Burr random variate Y can be transformed to the sample statistic X by the standardized procedure as follows:

$$\frac{Y - M}{S} = \frac{\bar{X} - \mu}{\sigma / \sqrt{n}} \quad (13)$$

That is, the scale and origin of the fitted Y values are changed to those of the X values, and from Equation above, when the process is in-control, we obtain,

$$\bar{X} = \mu_0 + (Y - M) \frac{\sigma / \sqrt{n}}{S} \quad (14)$$

When the process is out-of-control, X is assumed to follow a Burr distribution with mean $\mu_0 + \delta\sigma$ and standard deviation σ / \sqrt{n} “(Chou 2004)”.

2.2.2.2. The Variable Sampling Interval (VSI) \bar{X} control chart

Assume that the distribution of measurements from a process is non-normally distributed, and has the mean μ and standard deviation σ . When an \bar{X} control chart (with centerline μ_0 ; the upper control limit $\mu_0 + k_1(\sigma/\sqrt{n})$ and the lower control limit $\mu_0 - k'_1(\sigma/\sqrt{n})$ where k_1 and k'_1 are not necessarily equal) is used for monitoring the process, a sample of size n is taken and calculated its sample mean at each sampling point to judge whether or not the process remains in-control state. If the sample mean \bar{X}_i plotted on the control \bar{X} chart goes beyond the control limits, then a signal will be given to inform the operator to search for the assignable cause. Otherwise, the process is considered being in-control, and the next sample is continually taken at next sampling point

In this situation, the control chart operates with fixed sampling interval (say h_1) regardless of \bar{X}_i which is said to be the FSI control chart.

For VSI control charts, if the sample mean falls inside the control limits, the monitored process is also considered stable as FSI chart. However, with a difference to the FSI charts, the next sampling interval will be a function of this sample mean. That is, the next sampling rate depends on the current sample mean.

Assume the VSI \bar{X} chart uses a finite number of sampling interval lengths, say h_1, h_2, \dots, h_m ; where $h_1 < h_2 < \dots < h_m$; and $m \geq 2$. The choice of a sampling interval can be made by a function $h(x)$ when the value of \bar{X}_i is measured. Burr distribution can be implemented for the economic design of the VSI chart in monitoring non-normal process data.

CHAPTER 3

THE PROPOSED METHOD AND THE MODEL

The methodology used in this study for the development of the new method (NM) is briefly presented in this section. First of all different data sets were created or collected from the industry to test the effectiveness of the OM and the NM. Matlab v.7 software was used for computations. A number of built-in functions were employed in Matlab environment for computations. These functions are explained in section 3.3 and a complete list of program codes is given in Appendix D.

3.1. The Data

Different types of data were used in this study. Two random selections of 10000 data points were generated in Matlab, the first being normally distributed while the second was non-normally distributed (chi-square distribution). In addition, industrial data about the fineness of Portland cement were collected from a local cement plant (Çimentoş A.Ş.).

3.1.1. Normally Distributed Random Data

Matlab v.7 commercial software was used to create the randomly selected normally distributed data set. 10000 randomly selected data were produced with an average of 20 and a standard deviation of 1 (Appendix A). Batches with as much as 1000 data were taken from this 10000 data stock. The first 1000 data (Figure 3.1) were named “normally distributed normal operation data (NDNOD)” and were used for calculation of the control limits.

3.1.2. Non-Normally Distributed Random Data

Matlab v.7 commercial software was again used to create the randomly selected non-normally distributed data set. 10000 randomly selected data points with a chisquare

non-normal distribution were created with 5 degrees of freedom (Appendix B). Batches with as much as 1000 data were taken from this 10000 data stock. The first 1000 data (Figure 3.2) were named “non-normally distributed normal operation data (NNDNOD)” and were used for calculation of the control limits.




Figure 3.1. Histogram of the normally distributed data used in this study (NDNOD).




Figure 3.2. Histogram of the non- normally distributed (chi-square) data used in this study (NNDNOD)

3.1.3. Industrial Data (ID)

Portland cement manufacture process starts with a rotary furnace step in which a semi-product of clinker is produced. The semi-product is fast-cooled to preserve the cement phases and milled in tube mills with heavy iron ball media. The tube mill is actually a tumbling ball mill. The product of the mill is a finely ground powder whose particle size and surface area are closely monitored as a process control tool. One of the most important parameters is the CPCT 90 micrometers (Cumulative Percent Coarser Than) which is the oversized weight percentage above a 90 micrometer sieve. This data is collected once in every hour. For effective cement hydration reaction this percentage must be controlled within predetermined limits. The percentage of milled product larger than (cumulative percent larger than: CPCT) the 90 micrometer sieve was measured and recorded (DACK 90) in the cement plant as a process control parameter.

There were a total of 1179 data points that were collected from the plant (Figure 3.3 and Appendix C). Average CPCT 90 micrometer value was 0.5614 with a standard deviation of 0.3262. The data was partitioned into two sets based on the observation that the process was out-of control after the 951st data point. Therefore the first part with 950 data points was called the ID for normal operation. The remaining 229 data points were for the out-of-control situation.

Histogram for industrial data is presented in Figure 3.4 for normal operation. In order to identify the type of the reference distribution with which the industrial data could be associated, a number of tests were done. As a result of the first visual inspection the data could be identified non-normal. Therefore, a chisquare type of distribution was attempted first. For this purpose the normplot function of Matlab was employed and the resulting graph is shown in Figure 3.5. When the crosses are located on the diagonal red line the distribution is normal. The more the crosses deviate away from the diagonal red line, the less becomes the normality. As can be seen in Figure 3.5. the ID used in this study was not normally distributed.




Figure 3.3. Complete industrial data used in this study.




Figure 3.4. Histogram for normal operation part (950 data points) of industrial data.




Figure 3.5. Check for normality of the ND part (950 data points) of the ID.

3.2. Proposed Methodology

SPC is usually carried out by plotting the control charts for normal operation data in order to check for violations that are outside the control limits. In this study, two separate control charts were produced from the normal operation data which was regarded as ideal, in-control situation. The first was the OM which utilized the well known Shewhart Control Chart approach while the second was developed in this study and was named the new method (NM).

3.2.1. The Shewhart Method (OM)

The theory of Shewhart control charts is given in section 2.2.1. Normal operation data (NDNOD) were analyzed to determine its standard deviation, upper and lower control limits via equations 2, 3, 4 and 5. Using these values the control chart was created. Different levels of shifts were imposed on the data to observe the control chart performance when the process gets out of control. In such a case operator intervention is required. Shifts as much as 0.1, 0.25, 0.5 and 1σ were made to the mean. In addition, the standard deviation was increased by 1.1, 1.25, 1.5 and 2. Finally, tests were

conducted to make sure the process could be returned to normal operation. Same procedure was repeated for NNDNOD.

3.2.2. The New Method (NM)

Shewhart charts (OM) are well known and effectively used for normally distributed data as a process control tool. However, they are known to be deficient in the monitoring of non-normally distributed data. Therefore, a new method is proposed in this thesis to create a control chart for non-normally distributed data. The method works by first computing a ksdensity function using the built-in function of Matlab (ksdensity). Secondly either a normpdf or a chi2pdf function is computed. The mathematical basis for the two functions is presented in section 3.3. When the data was normally distributed the error was calculated by taking the difference between ksdensity and normpdf via equation 16. For non-normally distributed data, however, the difference between ksdensity and chi2pdf was used for error calculation (Eq. 17). The control chart developed in the new method contained the error as a process control measure in contrast to the original data itself that was used in the OM.

Figures 3.6. and 3.7 show a typical pdf and ksdensity estimation by using the Matlab statistics toolbox. The ksdensity points distributed around pdf plot illustrate the behavior of the process. The difference between the points of ksdensity (ks) and pdf(pdf) gives the error(E). Normpdf ($npdf$) used for normal distribution and chi2pdf ($cpdf$) used for chi-square distribution.

$$E_n = ksn - npdf \quad (16)$$

$$E_c = ksc - cpdf \quad (17)$$

Lower and upper control limits were then computed following the same procedure with the OM. However, the variable in this case was the error, not the original data. Control limits in the NM could be created based on the assumption that the error was normally distributed.

The effects of shifts to the data were also investigated for non-normally distributed data. The program code was written in such a way that gradually out-of-

control data was added to the normal operation data and the effect of the appending process was observed on the NM error chart. Such error charts were plotted using batches of data with 500 data points.




Figure 3.6. Plots of ksdensity and normal probability density function (normpdf). Wavy line indicates the ksdensity estimate while the other smooth line shows pdf.




Figure 3.7. Plots of ksdensity and chi-square probability density function (chi2pdf). Wavy line indicates the ksdensity estimate while the other smooth line shows pdf.

3.3. Functions Used in Matlab

In this study, Matlab software was widely used for creation of control charts and for other computations. Some of the important built-in functions are explained below to help the reader.

3.3.1. Random Matrices from Normal Distribution (Normrnd)

The following commands illustrate how to call the Random matrices from normal distribution

$$R = \text{normrnd}(\mu, \sigma) \quad (18)$$

Returns a matrix of random numbers chosen from the normal distribution with parameters μ and σ . The size of R is the common size of μ and σ if both are matrices. If either parameter is a scalar, the size of R is the size of the other parameter. Alternatively, $R = \text{normrnd}(\mu, \sigma, M, N)$ returns an M by N matrix.

3.3.2. Normpdf and Chi2pdf

Probability distribution function (pdf) command in Matlab returns the ordinate of the normal distribution at a given x value. The pdf command is used when x is known and the corresponding y value, which is the relative frequency, on the curve is desired (Figure 3.8).




Figure 3.8. Visualization of the probability density function

A pdf is not a single function. Rather a pdf is a family of functions characterized by one or more parameters.

The pdf function call has the same general format for every distribution in the Statistics Toolbox of Matlab. The following commands illustrate how to call the pdf for the normal distribution.

$$Y = \text{normpdf}(x, \mu, \sigma) \quad (19)$$

This computes the normal pdf at each of the values in X using the corresponding parameters in mu and sigma. x , μ , and σ can be vectors, matrices, or multidimensional arrays that all have the same size. A scalar input is expanded to a constant array with the same dimensions as the other inputs. The parameters in σ must be positive.

The normal pdf is (Abramowitz and Stegun 1964).

$$y = f(x | \mu, \sigma) = \frac{1}{\sigma \sqrt{2\pi}} e^{-\frac{(x-\mu)^2}{2\sigma^2}} \quad (20)$$

3.3.3. Kernel Density Estimators (Ksdensity)

A data sample can be described by estimating its density in a nonparametric way. The ksdensity function does this by using a kernel smoothing function and an associated bandwidth to estimate the density.

There are several methods for choosing the interval width. These nonparametric estimators result in figures which are smoother than histograms, allowing easy recognition of characteristics such as outliers, skewness, and multimodality. Most of these methods have been employed to describe young and size distribution of each sample was analyzed by means of Kernel Density Estimators (KDE), a statistical method first proposed by Silverman (1986) and defined as:

$$M_o(z) = \int \hat{f}^2 - \frac{2}{n} \sum_i \hat{f}_{-i}(X_i) \quad (21)$$

where ,

\hat{f}^2 = density estimation of the variable x

n = number of observations
 z = bandwidth
 X_i = length of the i -th fish specimen

$[F, Xi]=ksdensity(X)$ computes a probability density estimate of the sample in the vector X .

Ksdensity evaluates the density estimate at 100 points covering the range of the data. F is the vector of density values and X_i is the set of 100 points. The estimate is based on a normal kernel function, using a window parameter (bandwidth) that is a function of the number of points in X .

$F=ksdensity(X, Xi)$ specifies the vector X_i of values where the density estimate is to be evaluated. $[F, Xi,U]=ksdensity(...)$ also returns the bandwidth of the kernel smoothing window.

$[...]=ksdensity(...,'PARAM1',val1,'PARAM2',val2,...)$ specifies parameter name/value pairs to control the density estimation. Valid parameters are the following:

kernel : The type of kernel smoother to use, chosen from among 'normal' (default), 'box', 'triangle', and 'epanechnikov'.

Npoints : The number of equally-spaced points in XI .

Width : The bandwidth of the kernel smoothing window. The default is optimal for estimating normal densities, a smaller value to reveal features such as multiple modes can be chosen (Bowman and Azzalini 1997). In this thesis, this value was taken as 0.075 for the randomly selected data (NDD and NNDD) and as 0.05 for the industrial data (ID). The second value (0.05) was smaller because the numerical value of the industrial data (range from 0 to 1.4) was smaller.

3.3.4. Normal Cumulative Distribution Function (normcdf) and Chi-square Cumulative Distribution Function (chi2cdf)

Cdf computes a chosen cumulative distribution function. $P = cdf (NAME,X,A)$ returns the named cumulative distribution function, which uses parameter A , at the values in X . Similarly for $P = cdf (NAME,X,A,B,C)$. The name can be: 'beta' or 'Beta', 'bino' or 'Binomial', 'chi2' or 'Chisquare', 'exp' or 'Exponential', 'ev' or 'Extreme Value', 'f' or 'F', 'gam' or 'Gamma', 'geo' or 'Geometric', 'hyge' or 'Hypergeometric', 'logn' or 'Lognormal', 'nbin' or 'Negative Binomial', 'ncf' or 'Noncentral F', 'nct' or 'Noncentral t',

'ncx2' or 'Noncentral Chi-square', 'norm' or 'Normal', 'poiss' or 'Poisson', 'rayl' or 'Rayleigh', 't' or 'T', 'unif' or 'Uniform', 'unid' or 'Discrete Uniform', 'wbl' or 'Weibull'.

CDF calls many specialized routines that do the calculations. $P = cdf('name', X, A1, A2, A3)$ returns a matrix of probabilities, where name is a string containing the name of the distribution, X is a matrix of values, and A , $A2$, and $A3$ are matrices of distribution parameters. Depending on the distribution, some of these parameters may not be necessary. Vector or matrix inputs for X , $A1$, $A2$, and $A3$ must have the same size, which is also the size of P . A scalar input for X , $A1$, $A2$, or $A3$ is expanded to a constant matrix with the same dimensions as the other inputs. cdf is a utility routine allowing you to access all the cdfs in the Statistics Toolbox by using the name of the distribution as a parameter.

3.3.4.1. Normal Cumulative Distribution Function (Normcdf)

$$P = normcdf(X, \mu, \sigma)$$

$$[P, PLO, PUP] = normcdf(X, \mu, \sigma, PCOV, alpha)$$

$normcdf(X, \mu, \sigma)$ computes the normal cdf at each of the values in X using the corresponding parameters in μ and σ . X , μ , and σ can be vectors, matrices, or multidimensional arrays that all have the same size. A scalar input is expanded to a constant array with the same dimensions as the other inputs. The parameters in σ must be positive. $[P, PLO, PUP] = normcdf(X, \mu, \sigma, PCOV, \alpha)$ produces confidence bounds for P when the input parameters μ and σ are estimates. $PCOV$ is the covariance matrix of the estimated parameters. α specifies $100(1 - \alpha)\%$ confidence bounds. The default value of α is 0.05. PLO and PUP are arrays of the same size as P containing the lower and upper confidence bounds. The function $normcdf$ computes confidence bounds for P using a normal approximation to the distribution of the estimate and then transforming those bounds to the scale of the output P . The computed bounds give approximately the desired confidence level when you estimate μ , σ , and $PCOV$ from large samples, but in smaller samples other methods of computing the confidence bounds might be more accurate. The normal cdf is the result, p , is the probability that a single observation from a normal distribution with parameters μ and σ will fall in the interval $(-x]$. The standard normal distribution has $\mu = 0$ and $\sigma = 1$.

3.3.4.2. Chi- square Cumulative Distribution Function (chi2cdf)

$P = \text{chi2cdf}(X,V)$ computes the `chi2cdf` at each of the values in X using the corresponding parameters in V . X and V can be vectors, matrices, or multidimensional arrays that have the same size. A scalar input is expanded to a constant array with the same dimensions as the other input. The degrees of freedom parameters in V must be positive integers, and the values in X must lie on the interval $[0, 1]$. The `chi2cdf` for a given value x and ν degrees-of- freedom is where Γ is the Gamma function. The result, p , is the probability that a single observation from a chi2 distribution with ν degrees of freedom will fall in the interval $[0, x]$. The chi2 density function with ν degrees-of- freedom is the same as the gamma density function with parameters $\nu/2$ and 2.

CHAPTER 4

RESULTS AND DISCUSSION

In this chapter the results of OM and NM are given and compared for normally and non-normally distributed data as well as for industrial data.

4.1. Results of OM and NM for Normally Distributed Data

Normally distributed random data that was described in section 3.1.1 was used to plot the control charts. Two different techniques were used to create these charts: Shewhart control chart called the old method in this study (OM) and the new method (NM) that was developed in this thesis.

Upper and lower control limits of the OM charts were computed using the procedure described in section 2.2.1. The resulting Shewhart control charts (OM) are shown in Figure 4.1. As can be seen from the figure, the data is obviously normally distributed and there are very few data that are outside of the control limits.

Additional batches of randomly selected data of 500 data points were taken from the initial large random data set of 10000 members. These 500 data sets were shifted by addition of 0.1, 0.25, 0.5 and 1 to the mean. The purpose for imposing shifts to the data was to find out how the resulting control charts would be affected. Of course the mean increased and this was observed on the control chart (Figures 4.2-4.5). As a result of the increase in the mean the total number of violations was observed to increase in the UCL (upper control limit) area of the graph. This result was expected and the OM procedure was confirmed.

Table 4.1 shows the different scenarios that were tested in this study. Three different types of data were tested in the in-control and out of control situation for both the OM and the NM.

Table 4.1. List of the figures which show the progression of error charts in this study.

| | | Type of Data | | |
|--------------------|----|-------------------|-------------------|-------------|
| | | NDD | NNDD | ID |
| In-Control | OM | Figure 4.1 | Figure 4.22 | Figure 4.35 |
| | NM | Figure 4.11 | Figure 4.28 | Figure 4.38 |
| Out-of-control | OM | Figures 4.2-4.9 | Figures 4.23-4.26 | Figure 4.36 |
| | NM | Figures 4.12-4.19 | Figures 4.29-4.32 | Figure 4.39 |
| Back to in-control | OM | Figure 4.10 | Figure 4.27 | |
| | NM | Figures 4.20-4.21 | Figures 4.33-4.34 | |

4.1.1. Application of OM for $\alpha = 0.01$

In this section the control charts for an α value of 0.01 are given (Figures 4.1-4.9). When the α value increases the L coefficient in UCL or LCL calculation is decreased and hence the control limits are narrower. The progression of the increase in the number of violations (out-of-the control limits) with an increase in the amount of shift of the mean (Figures 4.2-4.5) and the standard deviation (Figure 4.6-4.9) can be clearly observed. In Figure 4.10 the capability to return back to normal operation is tested and demonstrated. This was achieved by appending the already shifted data with in-control data.

The lower and upper control limits are calculated for two different α values. This was done to check how much a narrower control interval could lead to an increase in the number of violations.




Figure 4.1. Shewhart control chart for normally distributed random data.




Figure 4.2. Shewhart control chart for normally distributed random data after its mean is shifted by 0.1 unit.




Figure 4.3. Shewhart control chart for normally distributed random data after its mean is shifted by 0.25 unit.




Figure 4.4. Shewhart control chart for normally distributed random data after its mean is shifted by 0.5 unit.




Figure 4.5. Shewhart control chart for normally distributed random data after its mean is shifted by 1 unit.




Figure 4.6. Shewhart control chart for normally distributed random data after its std is increased by 0.1 unit. The new standard deviation is 1.1.




Figure 4.7. Shewhart control chart for normally distributed random data after its std is increased by 0.25 unit. The new standard deviation is 1.25.




Figure 4.8. Shewhart control chart for normally distributed random data after its std is increased by 0.5 unit. The new standard deviation is 1.5.




Figure 4.9. Shewhart control chart for normally distributed random data after its mean is shifted by 1 unit. The new standard deviation is 2.




Figure 4.10. Shewhart control chart for normally distributed random data after the data is modified to return it back to normal operation.

4.1.2. Application of NM for $\alpha = 0.01$

In this section the results of the NM are given on control charts that were developed with control limits calculated for an α value of 0.01. In Figure 4.11 the error chart for normally distributed data (NDD) is presented for the in-control situation upon application of the new method (NM). The same data (NDD) was purposefully shifted to observe its response on the error charts (Figures 4.12-4.19). In Figures 4.20 and 4.21 the capability to return back to normal operation is tested and demonstrated. This was achieved by appending the already shifted data with in-control data.




Figure 4.11. Error control chart for NM for normally distributed random data when the operation is in-control.




Figure 4.12. Error chart for normally distributed data after its mean is shifted by 0.1 unit.




Figure 4.13. Error chart for normally distributed data after its mean is shifted by 0.25 unit.




Figure 4.14. Error chart for normally distributed data after its mean is shifted by 0.5 unit.




Figure 4.15. Error chart for normally distributed data after its mean is shifted by 1 unit.




Figure 4.16. Error chart for normally distributed data after its std is increased by 0.1 unit. The new standard deviation is 1.1.




Figure 4.17. Error chart for normally distributed data after its std is increased by 0.25 unit. The new standard deviation is 1.25.




Figure 4.18. Error chart for normally distributed data after its std is increased by 0.5 unit. The new standard deviation is 1.5.




Figure 4.19. Error chart for normally distributed data after its std is increased by 1. unit. The new standard deviation is 2.




Figure 4.20. Plots of ksdensity and normal probability density function (normpdf) after the data is modified to return it back to normal operation. Wavy line indicates the ksdensity estimate while the other smooth line shows pdf.




Figure 4.21. Error control chart for normally distributed random data after the data is modified to return it back to normal operation.

4.2. Results of OM and NM for Non-normally Distributed Data

Non-normally distributed random data that was described in section 3.1.2 was used to plot the control charts. OM and the NM were used for this non-normally distributed data (NNDD) as well.

The Shewhart control chart (OM) is shown in Figure 4.22. As can be seen from the figure, the data is obviously non-normally distributed and there are many data points that are outside of the control limits. These violations are unevenly located. There is no violation below the LCL when all violations are located above the UCL. This confirmed that the Shewhart control charts cannot be used for NNDD. Therefore, a new method is necessary for monitoring such data.

It should be noted that from this point on the OM is not used because it was identified to be unfit for NNDD. The NM was, however, further tested by giving shifts to the randomly selected NNDD.

Additional batches of randomly selected data of 500 data points were taken from the initial large random data set of 10000 members. These 500 data sets were shifted by 0.1, 0.25, 0.5 and 1. The purpose for imposing shifts to the data was to find out how the resulting control charts would be affected.

4.2.1. Application of the OM for $\alpha = 0.01$

In this section the control charts for an α value of 0.01 are given (Figures 4.22-4.26). As a result of the increase in the mean the total number of violations was not found to change significantly (Figures 4.23-4.26). In Figure 4.27 the capability to return back to normal operation is tested and marginally achieved. This was done by appending the already shifted data with in-control data. The resulting plot, however, contained a higher number of out-of-control data points leaving the impression that OM cannot be used for NNDD.




Figure 4.22. Shewhart control chart for non-normally distributed random data for in-control situation.




Figure 4.23. Shewhart control chart for non-normally distributed random data after it is shifted by 0.1 unit.




Figure 4.24. Shewhart control chart for non-normally distributed random data after it is shifted by 0.25 unit.




Figure 4.25. Shewhart control chart for non-normally distributed random data after it is shifted by 0.5 unit.




Figure 4.26. Shewhart control chart for non-normally distributed random data after it is shifted by 1 unit.




Figure 4.27. Shewhart control chart for non-normally distributed random data after the data is modified to return it back to normal operation.

4.2.2. Application of the NM for $\alpha = 0.01$

In this section the results of the NM are given on control charts that were developed with control limits calculated for an α value of 0.01. In Figure 4.28 the error chart for non-normally distributed data (NNDD) is presented for the in-control situation upon application of the new method (NM). The same data (NDD) was purposefully shifted to observe its response on the error charts (Figures 4.29-4.32). The number of violations significantly increased even with the smallest amount of shift (0.01) and remained roughly the same for higher amounts of shifts. In Figures 4.33 and 4.34 the capability to return back to normal operation is tested and demonstrated. This was achieved by appending the already shifted data with in-control data.




Figure 4.28. Error chart for chi-square distributed data (NNDD) for in-control situation.




Figure 4.29. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.1 unit.




Figure 4.30. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.25 unit.




Figure 4.31. Error chart for chi-square distributed data (NNDD) after it is shifted by 0.5 unit.




Figure 4.32. Error chart for chi-square distributed data (NNDD) after it is shifted by 1 unit.




Figure 4.33. Plots of ksdensity and chi-square probability density function (chi2pdf) after the process is returned back to in-control situation. Wavy line indicates the ksdensity estimate while the other smooth line shows pdf.




Figure 4.34. Error chart for chi-square distributed data (NNDD) after the process is returned back to in-control situation.

4.3. Results of OM and NM for Industrial Data

Non-normally distributed industrial data that was described in section 3.1.3 was used to plot the control charts. OM and the NM were used for this non-normally distributed industrial data (NND-ID) as well. The histogram for this data for in-control situation is shown in Figure 3.4. The NND-ID used in this study looked non-normal and skewed to the right. The same result was clear from Figure 3.5 where the normal probability plot of the NND-ID is given. The diagonal red line on the figure shows the conformity to normal distribution and any deviation from this line is an indication of non-normality.

4.3.1. Application of OM for $\alpha = 0.01$

The Shewhart control chart (OM) is shown in Figure 4.35. As can be seen from the figure, the data is obviously non-normally distributed and there are several data points that are outside of the control limits. These violations are unevenly distributed. There is only one violation below the LCL when all other violations are located above the UCL. This confirmed that the Shewhart control charts cannot be used for NND-ID. Therefore, a new method is necessary for monitoring such industrial data.

OM was applied to the out of control part of the industrial data and the results are given in Figure 4.36. The OM appears to successfully identify the out of control situation. But this was observed only above the UCL line, there was no violation below the LCL line.




Figure 4.35. Shewhart control chart for industrial data for normal operation




Figure 4.36. Shewhart control chart for industrial data for out-of-control situation.

4.3.2. Application of the NM for $\alpha = 0.01$

In this section the results of the NM are given on control charts that were developed with control limits calculated for an α value of 0.01. In Figure 4.37 the plot for the two functions (ksdensity and pdf) used in this study is given. As can be seen from Figure 4.37, the two functions closely followed each other for the in-control situation. In Figure 4.38, the error chart for the non-normally distributed industrial data (NND-ID) is presented for the in-control situation upon application of the new method (NM). There were no violations in this error chart.

When the NND-ID was analyzed by NM in the out-of-control situation the error chart as shown in Figure 4.39 was obtained. In Figure 4.39 it was clear that the new method was successful in capturing the violations. Another significant achievement of the NM was that the violations occurred equally above the UCL and below the LCL. This could not be possible with the OM because of the nature of the data that cannot contain any negative values. The percentage of coarse fraction of cement remaining above a certain sieve cannot be negative.




Figure 4.37. Plots of ksdensity and normpdf for industrial data for the in-control situation Dark continuous line shows ksdensity values while the dots show pdf values.




Figure 4.38. Error chart for industrial data for normal operation




Figure 4.39. Error chart for industrial data for out-of-control situation

CHAPTER 5

CONCLUSIONS AND RECOMMENDATIONS FOR FUTURE STUDY

For normally distributed data (NDD) both methods (OM and NM) worked well for in-control situation. The OM contained a total of six false alarms while the NM had none. This is a burden on the OM because run rules must be created to determine whether the alarm signals are a part of an out-of-control situation or just assignable causes (Montgomery 2005). The NM removes this necessity and hence is more practical. The effects of shifts to mimic an out-of-control situation showed a gradual increase in the number of violations in both methods. Upon feeding in-control data both methods could be returned back to in-control status from out-of-control case.

Non-normally distributed data NNDD were used to test performance of both OM and NM. For in-control case the OM was found to be unsuccessful by causing a large number of violations. When changes to mean and standard deviation introduced, the OM was found to be insensitive and unable to capture such conditions. On the other hand, the NM was found to be successful in both the in-control and out-of-control cases. Small amounts of shifts (i.e. less than 0.01) could be quickly captured by the NM. The NM could also be easily returned back to normal operation by feeding in-control data.

ID were first tested for its underlying distribution and it was identified as an NNDD. Then both OM and NM were applied for the in-control case and several false violations were observed in the OM while the NM worked well without violations. When the out-of-control data were analyzed by OM and NM, the OM was found to provide violations that were all located above the UCL. This one-sided biased result was expected because of the type of the distribution. The NM, however, was very well in that regard. The violations occurred equally balanced above the UCL and below the LCL. The NM was successfully implemented and the task outlined in the aim of the study part (section 2.1.3) was achieved.

The approach of this study was mainly aimed at developing a control chart for non-normal data, not on the economic aspects of such NND processes.

More NND-ID must be collected to further check and confirm the utility of the NM. The author is optimistic that this would yield good results for better process

control. The effects of varying smoothing parameters, shift ratios and sample sizes can be tested. Care must be taken to collect ID with higher measurement precision. New method's performance can be compared against other methods based on ARL and ATS criteria.

REFERENCES

- Alexander, S. M., Dillman M. A., Usher, J. S., Damodaran, B. 1995. "Economic design of control charts using the Taguchi loss function," *Computers and Industrial Engineering*. Vol. 28, pp. 671-679.
- Amin, R., Reynolds, M. R. Jr., Bakir, S. T. 1995. "Nonparametric quality control charts based on the sign statistic," *Communications in Statistics*. Vol. 24, pp.1597-1623.
- Abramowitz, M. and Stegun, I. A. 1964. "Handbook of Mathematical Functions," 26.1.26.
- Bakir, S.T. 2004. "A Distribution-Free Shewhart Quality Control Chart Based on Signed-Ranks," *Quality Engineering*. Vol. 16, pp.613-623.
- Bai, D.S. and Choi, I.S. 1995. " \bar{X} and R control charts for skewed populations," *Journal of Quality Technology*. Vol. 27, pp. 120-131.
- Bowman, A.W. and Azzalini, A. 1997. "Applied Smoothing Techniques for Data Analysis," Oxford University.
- Burr, I.W. 1942. "Cumulative frequency distribution. Annals of Mathematical Statistics," Vol.13, pp. 215-232.
- Burr, I. W. 1967. "The effect of nonnormality on constants for X and R charts," *Industrial Quality Control*. pp. 563-569.
- Chang, Y.S., Bai, D.S. 2001. « Control charts for positively skewed populations with weighted standard deviations," *Quality and Reliability Engineering International*. Vol. 17, pp.397-406.
- Chen, Y.K. 2004. "Economic design of control charts for non-normal data using variable sampling policy," *International Journal of Production Economics*. Vol. 92, pp. 61-74.
- Chiu, W.K. 1975. "Economic design of attribute control charts," *Technometrics*. Vol. 17, pp.81-87.
- Chou, C.Y.; Chen, C.H.; Liu, H.R. 2000. "Economic-Statistical Design of \bar{X} Charts for Non-Normal Data by Considering Quality Loss," *Journal of Applied Statistics*. Vol. 27, pp. 939- 951.
- Chou, C.Y.; Chen, C.H.; Liu, H.R. 2004. "Effect of Nonnormality on the Economic Design of Warning Limit \bar{X} Charts," *Quality Engineering*. Vol. 16, pp. 567-575.

- Chou, C. Y. and Cheng, P.H. 1997. "Ranges control chart for non-normal data," *Journal of the Chinese*. Vol. 14, pp. 401-409.
- Chou, C.Y.; Li, M.H.C.; Wang, P.H. 2001. "Economic Statistical Design of Averages Control Charts for Monitoring a Process under Non-normality," *The International Journal of Advanced Manufacturing Technology*. Vol. 17, pp. 603-609.
- Dou, Y. and Ping, S. 2002. "One Sided Control Charts for The Mean of Positively Skewed Distributions," *The Quality Management*. Vol. 13, pp. 1021-1033.
- Duncan, A. J. 1956. "The economic design of \bar{x} charts used to maintain current control of a process," *Journal of the American Statistical Association*. Vol. 51, pp. 228-242.
- Montgomery, Douglas C. 2005. "Introduction to Statistical Quality Control", 5th edition, Wiley & Sons, Inc.
- Rahim, M. A. 1985. "Economic model of \bar{x} chart under non-normality and measurement errors," *Computers and Operations Research*. Vol. 12, pp. 291-299.
- Reynolds Jr, M.R., Amin, R.W., Arnold, J.C., Nachlas, J.A. 1988. "Charts with variable sampling interval," *Technometrics*. Vol 30, pp. 181-192.
- Saniga, E. M. and Shirland, L. E. 1977. "Quality control in practice: a survey", *Quality Progress*. Vol. 10, pp. 30-33.
- Saniga, E. M. 1989. "Economic statistical control chart designs with an application to \bar{x} and R charts," *Technometrics*. Vol. 31, pp. 313-320.
- Shewhart, W.A. 1931. "Economic Control of Quality of Manufactured Product," New Jersey.
- Tasi, H. T. 1990. "Probabilistic tolerance design for a subsystem under Burr Distribution using Taguchi's quadratic loss function," *Communications in Statistics*. Vol. 19, pp. 4679-4696.
- Yourstone, S. A. and Zimmer, W. J. 1992. "Non-normality and the design of control charts for averages," *Decision Sciences*. Vol. 23, pp. 1099-1113.
- Woodall, W. H. 1985. "The statistical design of quality control charts", *The Statistician*. Vol. 34, pp. 155-160.

APPENDICES

APPENDIX A

| Normally Distributed Data | | | | | | | |
|---------------------------|---------|---------|---------|---------|---------|---------|---------|
| 19.5674 | 20.7143 | 17.8293 | 19.7041 | 20.5690 | 20.6565 | 19.4535 | 17.9457 |
| 18.3344 | 21.6236 | 19.9408 | 18.5249 | 19.1783 | 18.8322 | 19.1532 | 20.1326 |
| 20.1253 | 19.3082 | 18.9894 | 19.7660 | 19.7344 | 19.5394 | 19.7537 | 21.5929 |
| 20.2877 | 20.8580 | 20.6145 | 20.1184 | 18.8122 | 19.7376 | 20.6630 | 21.0184 |
| 18.8535 | 21.2540 | 20.5077 | 20.3148 | 17.7977 | 18.7868 | 19.1458 | 18.4196 |
| 21.1909 | 18.4063 | 21.6924 | 21.4435 | 20.9863 | 18.6806 | 18.7987 | 19.9213 |
| 21.1892 | 18.5590 | 20.5913 | 19.6490 | 19.4814 | 20.9312 | 19.8801 | 19.3183 |
| 19.9624 | 20.5711 | 19.3564 | 20.6232 | 20.3274 | 20.0112 | 19.9347 | 18.9754 |
| 20.3273 | 19.6001 | 20.3803 | 20.7990 | 20.2341 | 19.3549 | 20.4853 | 18.7656 |
| 20.1746 | 20.6900 | 18.9909 | 20.9409 | 20.0215 | 20.8057 | 19.4045 | 20.2888 |
| 19.8133 | 20.8156 | 19.9805 | 19.0079 | 18.9961 | 20.2316 | 19.8503 | 19.5707 |
| 20.7258 | 20.7119 | 19.9518 | 20.2120 | 19.0529 | 19.0102 | 19.5652 | 20.0558 |
| 19.4117 | 21.2902 | 20.0000 | 20.2379 | 19.6256 | 21.3396 | 19.9207 | 19.6321 |
| 22.1832 | 20.6686 | 19.6821 | 18.9922 | 18.8141 | 20.2895 | 21.5352 | 19.5350 |
| 19.8636 | 21.1908 | 21.0950 | 19.2580 | 18.9441 | 21.4789 | 19.3935 | 20.3710 |
| 20.1139 | 18.7975 | 18.1260 | 21.0823 | 21.4725 | 21.1380 | 18.6526 | 20.7283 |
| 21.0668 | 19.9802 | 20.4282 | 19.8685 | 20.0557 | 19.3159 | 20.4694 | 22.1122 |
| 20.0593 | 19.8433 | 20.8956 | 20.3899 | 18.7827 | 18.7081 | 19.0964 | 18.6427 |
| 19.9044 | 18.3959 | 20.7310 | 20.0880 | 19.9588 | 19.9271 | 20.0359 | 18.9774 |
| 19.1677 | 20.2573 | 20.5779 | 19.3645 | 18.8717 | 19.6694 | 19.3725 | 21.0378 |
| 20.2944 | 18.9435 | 20.0403 | 19.4404 | 18.6507 | 19.1564 | 20.5354 | 19.6102 |
| 18.6638 | 21.4151 | 20.6771 | 20.4437 | 19.7389 | 20.4978 | 20.5529 | 18.6187 |
| 19.0781 | 19.1949 | 20.5689 | 19.0501 | 20.9535 | 19.0224 | 19.5532 | 21.0821 |
| 20.3155 | 20.5287 | 19.7444 | 20.7812 | 21.2781 | 21.4885 | 19.7963 | 20.1286 |
| 21.5532 | 20.2193 | 19.6225 | 19.2879 | 19.4522 | 20.1068 | 20.3271 | 19.2438 |
| 20.7079 | 19.8868 | 18.8929 | 19.9887 | 20.2608 | 21.8482 | 19.3270 | 19.9109 |
| 21.9574 | 20.3792 | 20.4855 | 19.9992 | 19.9868 | 19.7249 | 19.8507 | 17.9911 |
| 20.5045 | 20.9442 | 19.9950 | 19.7506 | 19.4197 | 22.2126 | 17.5510 | 21.0839 |
| 21.8645 | 17.8796 | 19.7238 | 20.3966 | 22.1363 | 21.5085 | 20.4733 | 19.0188 |
| 19.6602 | 19.3553 | 21.2765 | 19.7360 | 19.7424 | 18.0549 | 20.1169 | 19.3115 |
| 18.8602 | 19.2957 | 21.8634 | 18.3360 | 18.5905 | 18.3195 | 19.4089 | 21.3395 |
| 19.7889 | 18.9819 | 19.4774 | 18.9710 | 21.7701 | 19.4265 | 19.3453 | 19.0908 |
| 21.1902 | 19.8179 | 20.1034 | 20.2431 | 20.3255 | 19.8142 | 18.9193 | 19.5871 |
| 18.8838 | 21.5210 | 19.1924 | 18.7434 | 18.8810 | 20.0089 | 19.9523 | 19.4938 |
| 20.6353 | 19.9616 | 20.6804 | 19.6528 | 20.6204 | 20.8369 | 20.3793 | 21.6197 |

| | | | | | | | |
|---------|---------|---------|---------|---------|---------|---------|---------|
| 19.3986 | 21.2274 | 17.6354 | 19.0586 | 21.2698 | 19.2777 | 19.6696 | 20.0809 |
| 20.5512 | 19.3038 | 20.9901 | 18.8254 | 19.1040 | 19.2785 | 19.5001 | 18.9189 |
| 18.9002 | 20.0075 | 20.2189 | 18.9789 | 20.1352 | 19.7988 | 19.9640 | 18.8755 |
| 20.0860 | 19.2171 | 20.2617 | 19.5983 | 19.8610 | 19.9795 | 19.8252 | 21.7357 |
| 17.9954 | 20.5869 | 21.2134 | 20.1737 | 18.8366 | 20.2789 | 19.0427 | 21.9375 |
| 19.5069 | 19.7488 | 19.7253 | 19.8839 | 21.1837 | 21.0583 | 21.2925 | 21.6351 |
| 20.4620 | 20.4801 | 19.8669 | 21.0641 | 19.9846 | 20.6217 | 20.4409 | 18.7441 |
| 19.6790 | 20.6682 | 18.7295 | 19.7546 | 20.5362 | 18.2494 | 21.2809 | 19.7865 |
| 21.2366 | 19.9217 | 18.3364 | 18.4825 | 19.2836 | 20.6973 | 19.5023 | 19.8011 |
| 19.3687 | 20.8892 | 19.2964 | 20.0097 | 19.3444 | 20.8115 | 18.8813 | 20.3075 |
| 17.6748 | 22.3093 | 20.2809 | 20.0714 | 20.3144 | 20.6363 | 20.8076 | 19.4277 |
| 18.7684 | 20.5246 | 19.4588 | 20.3165 | 20.9131 | 21.3101 | 20.0412 | 19.7334 |
| 21.0556 | 19.9882 | 18.6665 | 19.8986 | 17.3650 | 20.0281 | 19.1237 | 19.7345 |
| 19.5124 | 20.8564 | 18.6546 | 20.4998 | 20.0559 | 22.3726 | 20.2293 | 20.7017 |
| 21.8625 | 20.2685 | 21.4819 | 19.1095 | 20.9443 | 19.2663 | 21.7513 | 19.4573 |
| 21.1069 | 20.6250 | 20.0327 | 20.1391 | 17.5760 | 19.9355 | 20.7532 | 20.9122 |
| 18.7724 | 18.9527 | 21.8705 | 19.7639 | 19.7762 | 18.5560 | 20.0650 | 19.8279 |
| 19.3301 | 21.5357 | 18.7910 | 19.9245 | 20.0581 | 20.6123 | 19.7072 | 19.6640 |
| 21.3409 | 20.4344 | 19.2174 | 19.6414 | 19.5754 | 18.6765 | 20.0828 | 20.5415 |
| 20.3881 | 18.0829 | 19.2327 | 17.9224 | 19.7971 | 19.3384 | 20.7662 | 20.9321 |
| 20.3931 | 20.4699 | 19.8928 | 19.8565 | 18.4869 | 19.8539 | 22.2368 | 19.4297 |
| 18.2927 | 21.2744 | 19.0229 | 21.3933 | 18.8736 | 20.2481 | 20.3269 | 18.5014 |
| 20.2279 | 20.6385 | 19.0360 | 20.6518 | 19.1850 | 19.9234 | 20.8633 | 19.9497 |
| 20.6856 | 21.3808 | 17.6208 | 19.6229 | 20.3666 | 21.7382 | 20.6794 | 20.5530 |
| 19.3632 | 21.3198 | 19.1618 | 19.3386 | 19.4139 | 21.6220 | 20.5548 | 20.0835 |
| 18.9974 | 19.0906 | 20.2573 | 20.2490 | 21.5374 | 20.6264 | 21.0016 | 21.5775 |
| 19.8144 | 17.6944 | 19.8162 | 19.6165 | 20.1401 | 20.0918 | 21.2594 | 19.6692 |
| 18.9460 | 21.7887 | 19.8324 | 19.4715 | 18.1372 | 19.1924 | 20.0442 | 20.7952 |
| 19.9285 | 20.3908 | 19.8830 | 20.0554 | 19.5458 | 19.5387 | 19.6859 | 19.2152 |
| 20.2792 | 20.0203 | 20.1685 | 21.2538 | 19.3479 | 18.5940 | 20.2267 | 18.7369 |
| 21.3733 | 19.5940 | 19.4988 | 17.4800 | 20.1033 | 19.6255 | 20.9967 | 20.6667 |
| 20.1798 | 18.4651 | 19.2949 | 20.5849 | 19.7794 | 19.5291 | 21.2159 | 21.5783 |
| 19.4580 | 20.2214 | 20.5082 | 18.9919 | 19.7210 | 17.5854 | 19.6724 | 18.8918 |
| 21.6342 | 18.6255 | 19.5791 | 18.6074 | 19.7226 | 19.3057 | 18.8418 | 19.9741 |
| 20.8252 | 19.1607 | 20.2291 | 18.6994 | 18.7063 | 18.6086 | 20.5801 | 18.8894 |
| 20.2308 | 19.7914 | 19.0405 | 19.3950 | 19.1116 | 20.3296 | 20.2398 | 20.7508 |
| 20.6716 | 20.7559 | 19.8540 | 18.5114 | 19.0135 | 20.5985 | 19.6491 | 20.5002 |
| 19.4919 | 20.5080 | 20.1319 | 20.2801 | 19.0172 | 19.0559 | 19.9869 | 20.3543 |
| 19.4408 | 20.3757 | 20.7445 | 20.5585 | 19.9284 | 20.1472 | 20.8921 | 19.4827 |
| 19.2466 | 19.0470 | 20.0755 | 20.3253 | 20.9778 | 21.4419 | 20.1733 | 19.8396 |
| 20.9258 | 20.7782 | 19.4734 | 19.6649 | 20.0183 | 20.6723 | 20.9232 | 18.9164 |
| 19.7515 | 19.9937 | 19.3145 | 19.6776 | 20.8180 | 20.1387 | 19.8214 | 18.0458 |
| 19.8502 | 20.5245 | 19.7316 | 19.6176 | 20.7023 | 19.1405 | 19.4783 | 19.0905 |

| | | | | | | | |
|---------|---------|---------|---------|---------|---------|---------|---------|
| 18.7416 | 21.3643 | 18.8117 | 19.0466 | 19.7687 | 19.2477 | 21.4320 | 19.9944 |
| 20.3126 | 20.4820 | 20.2486 | 20.2336 | 19.8863 | 21.2296 | 19.1299 | 18.2765 |
| 22.6903 | 19.2129 | 20.1025 | 21.2352 | 20.1279 | 21.1508 | 20.8075 | 21.2631 |
| 20.2897 | 20.7520 | 19.9590 | 19.4215 | 19.2006 | 19.3920 | 19.4894 | 19.3996 |
| 18.5772 | 19.8331 | 17.7524 | 19.4985 | 19.7614 | 20.8062 | 20.7435 | 17.9361 |
| 20.2468 | 19.1838 | 19.4892 | 20.7229 | 19.9105 | 20.2171 | 20.8479 | 20.1109 |
| 18.5642 | 22.0941 | 20.2492 | 20.0395 | 18.9767 | 19.6265 | 19.1701 | 21.4876 |
| 20.1486 | 20.0802 | 20.3692 | 21.5413 | 20.9375 | 19.1680 | 20.5330 | 20.0530 |
| 18.3069 | 19.0627 | 20.1792 | 18.2989 | 18.8683 | 20.2869 | 21.0328 | 20.1620 |
| 20.7192 | 20.6357 | 19.9627 | 18.9663 | 19.2893 | 18.1811 | 18.9480 | 19.9731 |
| 21.1418 | 21.6820 | 18.3967 | 19.2363 | 18.8305 | 18.4269 | 20.3621 | 20.1736 |
| 21.5519 | 20.5936 | 20.3394 | 22.1764 | 21.0654 | 22.0157 | 19.9632 | 20.8822 |
| 21.3836 | 20.7902 | 19.8689 | 20.4316 | 19.3196 | 19.9280 | 18.7724 | 20.1823 |
| 19.2419 | 20.1053 | 20.4852 | 19.5562 | 18.2742 | 22.6289 | 19.7249 | 20.7553 |
| 20.4427 | 19.8414 | 20.5988 | 20.0300 | 20.8132 | 19.7567 | 20.2137 | 20.2349 |
| 20.9111 | 20.8709 | 19.9140 | 19.6843 | 22.7316 | 20.4995 | 19.5995 | 19.4022 |
| 18.9259 | 19.8052 | 19.1053 | 20.4194 | 20.4111 | 19.4892 | 20.0649 | 20.0208 |
| 20.2018 | 21.3242 | 20.8121 | 21.1911 | 18.6931 | 20.7712 | 18.2420 | 20.8261 |
| 20.7629 | 19.8735 | 20.1095 | 20.8584 | 20.3838 | 17.3558 | 21.6867 | 19.9919 |
| 18.7118 | 19.2628 | 19.2245 | 20.2710 | 21.3059 | 18.9477 | 20.6256 | 20.1098 |
| 18.3455 | 19.3081 | 20.7748 | 21.2315 | 21.3171 | 20.2854 | 20.3274 | 18.8670 |
| 19.0096 | 20.6802 | 20.2450 | 19.0740 | 20.2280 | 19.8206 | 18.3534 | 19.3169 |
| 20.6852 | 18.9275 | 20.1650 | 19.8881 | 18.5704 | 18.5329 | 20.4287 | 19.7221 |
| 19.0251 | 20.8998 | 20.4062 | 19.1970 | 19.8503 | 21.3953 | 19.2628 | 20.6548 |
| 19.3933 | 17.8769 | 21.2160 | 18.3350 | 19.4950 | 20.4408 | 20.5649 | 18.7516 |
| 20.6868 | 20.2847 | 21.4484 | 19.0986 | 18.2709 | 20.5654 | 18.6158 | 19.4025 |
| 20.0200 | 19.2667 | 18.9749 | 20.5883 | 19.5825 | 19.3064 | 20.4603 | 19.5182 |
| 21.0638 | 19.2266 | 20.2054 | 20.5542 | 19.3850 | 20.8339 | 20.6294 | 20.9834 |
| 18.6590 | 20.1518 | 20.5889 | 19.5848 | 20.7208 | 17.7626 | 20.3798 | 21.7621 |
| 20.4795 | 19.6632 | 19.7360 | 20.0618 | 20.3394 | 21.0976 | 18.9867 | 21.4274 |
| 18.3660 | 20.9708 | 22.4953 | 20.4574 | 20.8828 | 19.9984 | 19.6528 | 20.9118 |
| 18.5573 | 19.8928 | 20.8559 | 20.1990 | 20.2842 | 18.3854 | 20.4419 | 20.3268 |
| 20.2938 | 21.0135 | 19.1490 | 20.2576 | 19.8545 | 18.7713 | 18.4098 | 20.0696 |
| 19.8596 | 19.5247 | 20.8119 | 22.0807 | 19.9104 | 20.2074 | 19.2986 | 18.5002 |
| 18.8697 | 20.0689 | 20.7002 | 17.7228 | 20.2892 | 20.2209 | 18.9224 | 19.5818 |
| 19.7075 | 20.3986 | 20.7599 | 20.3390 | 21.1648 | 18.9939 | 21.0022 | 19.9790 |
| 19.4175 | 21.1163 | 18.2871 | 20.2899 | 20.8057 | 19.5469 | 21.7295 | 20.2284 |
| 19.1037 | 20.6205 | 21.5370 | 20.6623 | 18.6444 | 21.3995 | 20.7090 | 18.9918 |
| 20.2486 | 19.7123 | 18.3902 | 19.4191 | 20.1209 | 19.5380 | 19.2521 | 19.3354 |
| 18.5103 | 18.6282 | 21.1095 | 20.8878 | 19.7778 | 20.0327 | 20.2289 | 20.5582 |
| 20.3135 | 19.3141 | 18.8903 | 20.1719 | 20.5717 | 20.7988 | 19.7765 | 18.8115 |
| 17.9749 | 20.3317 | 20.3855 | 20.8488 | 19.6999 | 20.8968 | 19.1467 | 20.8585 |
| 20.5290 | 19.0023 | 20.9652 | 20.9638 | 21.1343 | 20.1379 | 20.3456 | 17.8947 |

| | | | | | | | |
|---------|---------|---------|---------|---------|---------|---------|---------|
| 20.3435 | 20.2914 | 20.8183 | 21.3219 | 21.5350 | 18.3809 | 19.3978 | 18.5861 |
| 20.7582 | 19.7933 | 19.5744 | 20.4938 | 19.1291 | 20.0798 | 19.4784 | 19.6157 |
| 20.5536 | 21.1071 | 20.0370 | 19.9357 | 19.2024 | 19.6865 | 21.2591 | |
| 19.5421 | 19.6391 | 19.7085 | 19.6988 | 18.4114 | 21.0943 | | |

APPENDIX B

| Non-Normally Distributed Data | | | | | | | |
|-------------------------------|---------|---------|---------|---------|---------|---------|---------|
| 3.1806 | 4.2753 | 1.9871 | 8.4224 | 3.5193 | 2.0197 | 2.7189 | 0.5458 |
| 1.0469 | 3.8881 | 6.4056 | 0.8265 | 1.2798 | 4.9880 | 2.8859 | 7.9339 |
| 4.7129 | 1.1187 | 6.0065 | 5.7200 | 3.6803 | 5.0720 | 5.7750 | 2.9788 |
| 5.2366 | 5.1358 | 11.4692 | 7.5410 | 4.6915 | 1.9921 | 2.0953 | 5.3703 |
| 1.7586 | 1.9079 | 6.3175 | 6.8611 | 5.3277 | 2.4953 | 7.0639 | 5.0595 |
| 8.8698 | 9.9771 | 2.7014 | 6.2668 | 10.1234 | 8.3642 | 6.2334 | 4.3968 |
| 8.8615 | 2.3691 | 5.5522 | 4.4531 | 3.3800 | 3.9576 | 2.3365 | 1.9988 |
| 4.2235 | 6.0837 | 1.9897 | 6.6479 | 6.4392 | 5.5854 | 3.5975 | 2.1003 |
| 5.3700 | 5.0116 | 4.2761 | 6.2332 | 7.1370 | 4.5976 | 1.6928 | 5.9248 |
| 4.8681 | 2.1465 | 4.1929 | 3.6235 | 7.7353 | 2.2940 | 6.5930 | 2.8060 |
| 3.8066 | 0.5696 | 4.3335 | 3.3144 | 5.2427 | 5.9701 | 2.2737 | 3.9075 |
| 6.8404 | 4.1614 | 3.4633 | 1.6532 | 10.3081 | 10.3584 | 1.6716 | 3.1753 |
| 2.8219 | 3.3219 | 1.4513 | 7.6935 | 8.6212 | 2.9154 | 3.9899 | 4.1040 |
| 14.4616 | 1.6958 | 3.6092 | 4.3665 | 2.6152 | 2.2880 | 6.1669 | 10.6059 |
| 3.9441 | 1.9089 | 7.7899 | 2.6980 | 1.5342 | 8.1630 | 1.8350 | 2.7819 |
| 4.6775 | 10.2743 | 4.7232 | 7.1645 | 4.1222 | 3.2841 | 4.5914 | 4.5001 |
| 8.2936 | 4.4995 | 6.5675 | 5.0516 | 1.9628 | 1.4063 | 0.7056 | 1.8230 |
| 4.5102 | 1.6468 | 1.7244 | 2.0238 | 1.6206 | 5.3302 | 3.0378 | 5.9255 |
| 4.0578 | 4.2131 | 3.1139 | 10.9179 | 5.2404 | 10.7029 | 5.8409 | 4.3186 |
| 2.3158 | 2.7360 | 3.7609 | 8.0761 | 3.1884 | 6.7692 | 3.4554 | 3.5700 |
| 5.2591 | 6.1083 | 0.6628 | 1.1472 | 4.4997 | 13.0274 | 9.0882 | 9.2820 |
| 1.4699 | 6.1733 | 4.7354 | 4.1059 | 3.3381 | 5.9948 | 2.7279 | 2.9698 |
| 6.7948 | 5.2139 | 4.3002 | 3.6016 | 3.1036 | 12.4662 | 0.4599 | 7.3749 |
| 11.0856 | 2.9274 | 4.3309 | 1.0487 | 5.5197 | 3.4080 | 1.6248 | 5.1728 |
| 2.5992 | 1.4737 | 3.6397 | 1.9551 | 6.8504 | 1.7695 | 8.2432 | 6.4459 |
| 7.3818 | 8.3205 | 5.6088 | 5.0891 | 13.9997 | 3.7410 | 4.0085 | 1.9235 |
| 9.1726 | 2.5569 | 1.8670 | 1.5869 | 1.4399 | 8.8666 | 5.5484 | 10.6087 |
| 1.1311 | 1.0299 | 4.1943 | 3.3895 | 1.9662 | 6.4855 | 7.7497 | 5.7422 |
| 1.3249 | 2.8547 | 5.5488 | 2.1108 | 3.0075 | 2.7930 | 0.6087 | 0.7851 |
| 6.2416 | 3.8090 | 3.4317 | 1.7137 | 11.0646 | 1.6310 | 2.6990 | 5.8692 |
| 3.2595 | 4.3597 | 3.0220 | 1.9687 | 4.5759 | 2.6453 | 2.5730 | 9.2717 |
| 6.6986 | 7.2937 | 4.2283 | 3.2552 | 1.8663 | 9.6010 | 1.9740 | 6.4981 |
| 7.2053 | 2.5358 | 3.8389 | 4.8650 | 1.7943 | 5.5792 | 3.8191 | 9.8018 |
| 6.7852 | 2.5375 | 2.0820 | 4.0004 | 11.7145 | 5.5965 | 10.5305 | 9.4959 |
| 9.3496 | 3.7676 | 9.3609 | 8.2816 | 12.9055 | 1.0000 | 4.2212 | 2.1696 |
| 6.6147 | 4.2734 | 5.7653 | 3.6503 | 11.1491 | 5.0393 | 9.0443 | 0.4729 |
| 8.8694 | 5.2073 | 9.3040 | 1.2252 | 1.5878 | 6.6814 | 2.5899 | 12.0203 |
| 1.6698 | 8.2552 | 3.0270 | 4.3621 | 3.7346 | 2.7160 | 4.3555 | 5.5886 |

| | | | | | | | |
|--------|---------|---------|---------|---------|---------|---------|---------|
| 4.6450 | 6.4332 | 1.8038 | 4.5469 | 3.7737 | 2.0012 | 2.4130 | 4.3934 |
| 2.3640 | 0.9528 | 7.1724 | 5.3336 | 5.3031 | 3.8095 | 6.3011 | 3.2447 |
| 6.6610 | 6.7275 | 4.4558 | 5.9776 | 2.8574 | 1.9121 | 3.6351 | 1.2034 |
| 0.4344 | 7.1882 | 2.4666 | 9.2900 | 2.0454 | 4.1261 | 5.9061 | 5.0183 |
| 7.9506 | 6.4896 | 4.0762 | 2.9124 | 3.1466 | 5.2083 | 6.6130 | 1.4158 |
| 5.0102 | 9.4475 | 0.7018 | 5.1474 | 8.3633 | 9.7637 | 4.1068 | 2.4442 |
| 5.1502 | 5.3694 | 8.3716 | 4.2947 | 15.7433 | 4.8846 | 7.5134 | 4.0253 |
| 8.9772 | 2.6387 | 2.0391 | 2.8397 | 5.0440 | 2.9255 | 15.3066 | 2.0464 |
| 3.5740 | 3.9084 | 2.6061 | 14.1556 | 3.5949 | 11.1443 | 6.0686 | 2.0699 |
| 3.9531 | 5.8813 | 9.5937 | 3.6183 | 6.7446 | 7.2450 | 4.2987 | 0.4252 |
| 1.5660 | 4.6868 | 2.1699 | 1.3674 | 3.0506 | 5.0488 | 7.6157 | 2.3045 |
| 1.0492 | 2.8157 | 3.2280 | 11.9123 | 12.4540 | 6.6265 | 4.3147 | 5.1359 |
| 2.5746 | 2.6776 | 3.6057 | 5.3641 | 8.4768 | 3.0031 | 6.0680 | 3.8144 |
| 5.0435 | 3.7630 | 11.0769 | 6.4282 | 3.4176 | 2.5938 | 9.7182 | 3.8584 |
| 2.0780 | 1.2309 | 6.4515 | 9.2494 | 6.1309 | 1.3923 | 5.9130 | 3.9980 |
| 3.9175 | 1.7913 | 4.6093 | 2.1945 | 7.6974 | 5.3780 | 2.4047 | 4.8485 |
| 6.9155 | 2.3496 | 2.3641 | 4.7436 | 2.8620 | 6.3450 | 6.9456 | 3.0190 |
| 2.2049 | 5.5047 | 3.1121 | 3.9368 | 1.2494 | 4.7812 | 3.8604 | 2.5714 |
| 4.7557 | 2.8268 | 1.3722 | 1.7315 | 4.1868 | 4.0415 | 2.3472 | 6.0081 |
| 3.6747 | 4.7589 | 3.3216 | 8.8357 | 6.1738 | 4.4164 | 13.8836 | 3.2085 |
| 4.1150 | 0.8375 | 3.0896 | 4.2881 | 4.5838 | 2.2316 | 4.5736 | 3.3023 |
| 3.3611 | 3.1290 | 11.8040 | 6.1114 | 10.8340 | 3.5978 | 2.1183 | 2.0890 |
| 0.6433 | 2.6832 | 6.9505 | 2.5479 | 3.4307 | 3.4387 | 6.4873 | 5.0580 |
| 3.9243 | 4.6447 | 4.5275 | 2.6757 | 7.1210 | 1.7397 | 11.4107 | 9.0819 |
| 9.8656 | 3.7157 | 3.5273 | 5.3262 | 2.4092 | 6.2751 | 6.3264 | 2.8436 |
| 6.5494 | 3.5627 | 4.5818 | 4.6555 | 1.5770 | 5.0782 | 7.1005 | 3.0182 |
| 3.3152 | 2.5125 | 7.0029 | 12.3693 | 6.6071 | 3.3803 | 4.6506 | 6.8287 |
| 2.6632 | 4.1461 | 14.8173 | 3.5729 | 1.3906 | 7.5259 | 3.8831 | 4.4507 |
| 5.1083 | 1.3209 | 5.3687 | 14.6556 | 1.5215 | 10.8383 | 7.4361 | 10.6387 |
| 3.2995 | 6.3975 | 7.4041 | 10.4642 | 2.7851 | 1.8212 | 3.7849 | 1.0069 |
| 2.9563 | 1.4882 | 6.6569 | 2.6204 | 1.2623 | 4.2574 | 4.5593 | 1.9469 |
| 4.4984 | 2.6629 | 6.1803 | 4.4646 | 6.1944 | 1.8171 | 2.9605 | 2.4515 |
| 9.1715 | 3.9173 | 8.0015 | 3.4728 | 3.5670 | 6.9409 | 2.6124 | 14.4172 |
| 6.2932 | 5.1055 | 1.7217 | 5.0356 | 1.5316 | 5.9789 | 3.5903 | 5.7322 |
| 1.9916 | 4.1116 | 8.2875 | 7.9796 | 2.2088 | 2.9820 | 1.6919 | 3.1538 |
| 7.7501 | 11.7288 | 2.6231 | 8.9890 | 2.0296 | 2.8867 | 5.1071 | 4.4222 |
| 0.3977 | 1.7881 | 0.9797 | 2.9240 | 4.1259 | 2.4723 | 4.6420 | 3.4689 |
| 3.7072 | 7.1719 | 7.1953 | 7.6118 | 0.4034 | 7.6702 | 4.2137 | 7.8965 |
| 4.5065 | 2.9972 | 10.1149 | 3.8461 | 7.8655 | 3.6421 | 0.5130 | 4.3874 |
| 3.1996 | 6.9114 | 6.6290 | 2.8009 | 4.0252 | 3.9070 | 2.9969 | 7.2149 |
| 2.2635 | 7.3394 | 4.7545 | 4.3948 | 8.0541 | 1.5841 | 5.1093 | 6.7473 |
| 2.4746 | 2.3206 | 0.7507 | 5.6891 | 3.0792 | 5.3204 | 5.5136 | 3.6875 |
| 9.0547 | 6.0994 | 2.1695 | 8.8707 | 4.5395 | 18.0582 | 4.8826 | 4.0072 |

| | | | | | | | |
|---------|---------|---------|--------|---------|---------|---------|---------|
| 8.6806 | 8.1406 | 4.3169 | 7.0233 | 5.6159 | 5.2433 | 4.2245 | 4.7210 |
| 2.7785 | 1.9155 | 0.9822 | 0.2798 | 8.5205 | 1.3493 | 1.1196 | 2.3803 |
| 7.1662 | 5.4892 | 9.2167 | 5.2291 | 6.4286 | 5.1012 | 5.4112 | 3.6682 |
| 5.0045 | 4.2259 | 2.7952 | 7.2486 | 3.5404 | 1.3319 | 3.9586 | 4.0753 |
| 3.3243 | 1.6309 | 4.6681 | 4.3095 | 1.4195 | 4.7856 | 5.9244 | 1.9651 |
| 2.3164 | 3.5729 | 10.3538 | 7.3836 | 2.6116 | 1.0158 | 6.3458 | 7.7208 |
| 5.2339 | 3.8780 | 4.4912 | 7.0379 | 5.3850 | 6.8141 | 4.0850 | 1.7826 |
| 0.8814 | 1.8621 | 4.8279 | 9.4270 | 2.0098 | 8.6386 | 5.3632 | 2.5597 |
| 13.3880 | 6.6600 | 4.2547 | 9.0638 | 5.2491 | 10.6959 | 3.4197 | 7.3732 |
| 4.1249 | 1.8807 | 4.8647 | 7.8122 | 8.4778 | 9.8162 | 3.4517 | 2.2799 |
| 17.5944 | 7.5586 | 7.4837 | 1.0596 | 5.0952 | 2.4628 | 1.9618 | 7.1898 |
| 3.6558 | 0.6065 | 4.8925 | 2.0227 | 4.8374 | 5.7715 | 4.9666 | 6.7390 |
| 4.8637 | 5.2267 | 6.9589 | 6.6798 | 5.6426 | 7.6070 | 6.3084 | 6.9776 |
| 7.6590 | 2.5132 | 6.0076 | 2.0504 | 8.9893 | 1.8781 | 3.6016 | 0.9938 |
| 3.8287 | 2.4320 | 4.7333 | 2.7814 | 10.1489 | 4.9549 | 16.6123 | 10.6159 |
| 2.9718 | 4.7959 | 5.2113 | 6.6860 | 7.8413 | 6.9895 | 2.1389 | 1.1119 |
| 10.0637 | 3.4154 | 2.0361 | 4.3926 | 7.2163 | 1.5397 | 4.0121 | 8.4891 |
| 2.2434 | 6.5900 | 2.1059 | 8.2801 | 4.4433 | 2.0898 | 2.3731 | 1.8186 |
| 6.3064 | 2.8384 | 4.2950 | 1.4630 | 5.0399 | 7.0516 | 1.0476 | 5.5701 |
| 6.1780 | 7.5074 | 5.4624 | 5.9038 | 1.3401 | 5.4111 | 2.1845 | 3.8265 |
| 3.2224 | 4.8593 | 2.1970 | 1.0834 | 3.9074 | 7.4866 | 7.1645 | 1.2904 |
| 4.5178 | 7.3433 | 7.1908 | 1.3227 | 3.0103 | 5.2251 | 1.4422 | 9.8758 |
| 5.8243 | 7.8349 | 4.6639 | 5.2570 | 0.9760 | 3.9188 | 4.6991 | 5.7650 |
| 4.9460 | 9.5062 | 18.3754 | 3.9331 | 3.2169 | 4.0747 | 3.7116 | 6.2200 |
| 5.1366 | 4.1467 | 5.6597 | 1.7848 | 2.7633 | 5.2416 | 6.2438 | 7.2809 |
| 13.7985 | 9.4820 | 1.5123 | 3.5279 | 6.8204 | 8.7466 | 3.5084 | 2.3024 |
| 5.4100 | 1.1008 | 5.5643 | 2.8347 | 2.6173 | 3.2150 | 8.6037 | 3.7477 |
| 5.2440 | 1.0687 | 5.9764 | 2.1939 | 3.5657 | 4.2717 | 2.9720 | 6.9614 |
| 0.5203 | 5.7219 | 2.9968 | 5.1072 | 6.5609 | 5.0412 | 1.3615 | 5.5363 |
| 8.4345 | 2.5052 | 5.0624 | 1.2609 | 1.5992 | 1.9914 | 3.2976 | 1.4567 |
| 4.3286 | 6.2183 | 9.1987 | 5.3234 | 2.8015 | 2.6564 | 3.1202 | 10.3236 |
| 1.1062 | 1.4023 | 1.8721 | 6.0846 | 3.0640 | 6.1930 | 3.5307 | 4.4304 |
| 1.6292 | 5.8345 | 8.0041 | 5.4252 | 7.9208 | 1.6916 | 3.5057 | 12.5015 |
| 4.9730 | 6.4628 | 11.6792 | 6.9706 | 11.8663 | 2.4278 | 1.1373 | 1.6597 |
| 5.0169 | 5.5505 | 6.7738 | 2.5988 | 10.0402 | 5.1812 | 8.4191 | 2.4135 |
| 1.9951 | 1.9824 | 2.4834 | 7.3838 | 7.6098 | 10.6049 | 9.5174 | 4.9934 |
| 3.1317 | 3.3894 | 5.0426 | 0.6208 | 5.3684 | 1.9151 | 3.9716 | 3.2579 |
| 9.8968 | 5.7688 | 3.7081 | 3.3552 | 4.5415 | 6.4481 | 2.5053 | 4.5273 |
| 3.1107 | 1.1353 | 2.2755 | 6.1758 | 1.2479 | 2.3838 | 4.1439 | 0.9449 |
| 4.4304 | 2.5790 | 5.4325 | 1.1766 | 3.4311 | 3.4743 | 2.9004 | 11.4372 |
| 7.1359 | 10.9490 | 4.6646 | 3.7530 | 3.7986 | 2.7913 | 5.2721 | 5.3704 |
| 2.4921 | 0.6540 | 1.7804 | 3.1974 | 3.5044 | 9.1972 | 1.6325 | 6.8013 |
| 4.8730 | 7.8051 | 4.7521 | 5.9556 | 9.5943 | 3.6478 | 4.5726 | 1.4540 |
| 6.0804 | 2.9452 | 2.1851 | 2.2419 | 7.5460 | | | |

APPENDIX C

| Industrial Data | | | | | | | | | | | | | | | |
|------------------------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 0.3 | 0.4 | 0.4 | 0.3 | 0.6 | 0.5 | 0.6 | 0.2 | 0.6 | 0.5 | 0.5 | 0.5 | 0.3 | 0.4 | 0.3 | 0.2 |
| 0.3 | 0.6 | 0.5 | 0.3 | 0.6 | 0.8 | 0.6 | 0.5 | 0.6 | 0.5 | 0.6 | 0.4 | 0.3 | 0.2 | 0.3 | 0.4 |
| 0.8 | 0.5 | 0.6 | 0.5 | 0.5 | 0.4 | 0.5 | 0.5 | 0.5 | 0.5 | 0.8 | 0.3 | 0.6 | 0.4 | 0.3 | 0.6 |
| 0.5 | 0.5 | 0.4 | 0.3 | 0.4 | 0.6 | 0.8 | 0.3 | 0.8 | 0.5 | 0.8 | 0.2 | 0.8 | 0.2 | 0.2 | 0.6 |
| 0.3 | 0.6 | 0.3 | 0.7 | 0.6 | 0.4 | 0.9 | 0.6 | 0.9 | 0.6 | 1.0 | 0.3 | 0.5 | 0.4 | 0.5 | 0.5 |
| 0.3 | 0.4 | 0.5 | 0.5 | 0.4 | 0.6 | 0.5 | 0.4 | 0.7 | 0.6 | 0.6 | 0.6 | 0.5 | 0.3 | 0.3 | 0.4 |
| 0.2 | 0.5 | 0.4 | 0.3 | 0.4 | 0.4 | 0.6 | 0.3 | 1.0 | 0.5 | 0.7 | 0.4 | 0.4 | 0.2 | 0.5 | 0.6 |
| 0.7 | 0.4 | 0.4 | 0.6 | 0.5 | 0.6 | 0.6 | 0.4 | 0.6 | 0.4 | 0.6 | 0.3 | 0.4 | 0.3 | 0.5 | 0.4 |
| 0.5 | 0.6 | 0.3 | 0.2 | 0.3 | 0.5 | 0.2 | 0.3 | 0.4 | 0.6 | 0.7 | 0.4 | 0.5 | 0.4 | 0.6 | 0.4 |
| 0.3 | 0.5 | 0.5 | 0.4 | 0.6 | 0.5 | 0.2 | 0.6 | 0.4 | 0.5 | 0.6 | 0.2 | 0.4 | 0.4 | 0.5 | 0.3 |
| 0.4 | 0.5 | 0.4 | 0.4 | 0.5 | 0.4 | 0.5 | 0.5 | 0.4 | 0.5 | 0.6 | 0.5 | 0.5 | 0.6 | 0.4 | 0.5 |
| 0.4 | 0.6 | 0.8 | 0.3 | 0.5 | 0.8 | 0.1 | 0.3 | 0.9 | 0.5 | 0.7 | 0.3 | 0.5 | 0.4 | 0.4 | 0.3 |
| 0.4 | 0.5 | 0.6 | 0.7 | 0.5 | 0.7 | 0.1 | 0.3 | 0.8 | 0.4 | 0.5 | 0.2 | 0.4 | 0.4 | 0.4 | 0.3 |
| 0.1 | 0.7 | 0.5 | 0.5 | 0.6 | 0.5 | 0.2 | 0.3 | 0.5 | 0.4 | 0.5 | 0.2 | 0.4 | 0.3 | 0.3 | 0.5 |
| 0.3 | 0.6 | 0.7 | 0.5 | 0.6 | 0.6 | 0.2 | 0.2 | 0.4 | 0.5 | 0.4 | 0.2 | 0.4 | 0.3 | 0.4 | 0.4 |
| 0.6 | 0.6 | 0.6 | 0.3 | 0.5 | 0.7 | 0.3 | 1.0 | 0.5 | 0.5 | 0.4 | 0.3 | 0.5 | 0.4 | 0.3 | 0.6 |
| 0.3 | 0.6 | 0.6 | 0.4 | 0.9 | 1.3 | 0.4 | 0.2 | 0.4 | 0.6 | 0.5 | 0.2 | 0.4 | 0.4 | 0.3 | 0.5 |
| 0.5 | 0.6 | 0.5 | 0.3 | 0.4 | 0.8 | 0.2 | 0.6 | 0.7 | 0.5 | 0.5 | 0.3 | 0.4 | 0.3 | 0.3 | 0.6 |
| 0.3 | 0.6 | 0.6 | 0.3 | 0.7 | 0.6 | 0.6 | 0.4 | 0.5 | 0.4 | 0.4 | 0.2 | 0.3 | 0.4 | 0.4 | 0.5 |
| 0.4 | 0.5 | 0.5 | 0.3 | 0.5 | 0.8 | 0.5 | 0.6 | 0.8 | 0.5 | 0.4 | 0.2 | 0.4 | 0.2 | 0.2 | 0.7 |
| 0.4 | 0.6 | 0.4 | 0.3 | 0.4 | 0.5 | 0.6 | 0.6 | 0.3 | 0.5 | 0.5 | 0.3 | 0.3 | 0.4 | 0.3 | 0.7 |
| 0.3 | 0.4 | 0.6 | 0.7 | 0.7 | 0.5 | 0.5 | 0.7 | 0.4 | 0.6 | 0.3 | 0.3 | 0.5 | 0.4 | 0.3 | 0.6 |
| 0.3 | 0.5 | 0.5 | 0.3 | 0.8 | 0.6 | 0.4 | 0.6 | 0.3 | 0.5 | 0.5 | 0.4 | 0.5 | 0.2 | 0.3 | 0.6 |
| 0.4 | 0.6 | 0.5 | 0.5 | 0.5 | 0.5 | 0.4 | 0.5 | 0.8 | 0.5 | 0.4 | 0.4 | 0.2 | 0.2 | 0.4 | 0.6 |
| 0.4 | 0.5 | 0.6 | 1.0 | 0.6 | 0.7 | 0.2 | 0.7 | 0.8 | 0.4 | 0.5 | 0.4 | 0.4 | 0.3 | 0.5 | 0.7 |
| 0.5 | 0.7 | 0.6 | 0.3 | 0.5 | 0.7 | 0.4 | 0.6 | 0.6 | 0.2 | 0.5 | 0.5 | 0.2 | 0.4 | 0.4 | 0.5 |
| 0.5 | 0.5 | 0.8 | 0.6 | 0.3 | 0.8 | 0.3 | 0.9 | 0.5 | 0.4 | 0.4 | 0.3 | 0.9 | 0.6 | 0.4 | 0.4 |
| 0.5 | 0.6 | 0.6 | 0.4 | 0.9 | 0.5 | 0.4 | 0.7 | 0.4 | 0.5 | 0.4 | 0.4 | 0.3 | 0.5 | 0.5 | 0.4 |
| 0.4 | 0.7 | 0.4 | 0.4 | 0.7 | 1.0 | 0.5 | 0.8 | 0.3 | 0.6 | 0.3 | 0.5 | 0.5 | 0.5 | 0.4 | 0.9 |
| 0.5 | 0.6 | 0.3 | 0.7 | 0.3 | 0.5 | 0.4 | 0.8 | 0.3 | 0.3 | 0.2 | 0.3 | 0.2 | 0.4 | 0.4 | 0.8 |
| 0.6 | 0.5 | 0.4 | 1.0 | 0.6 | 0.5 | 0.4 | 0.5 | 0.5 | 0.3 | 0.6 | 0.5 | 0.3 | 0.3 | 0.5 | 0.7 |
| 0.5 | 0.5 | 0.5 | 0.5 | 0.7 | 0.7 | 0.4 | 0.7 | 0.4 | 0.7 | 0.5 | 0.4 | 0.3 | 0.7 | 0.8 | 0.4 |
| 0.4 | 0.5 | 0.5 | 0.6 | 0.6 | 0.7 | 0.4 | 0.7 | 0.5 | 0.3 | 0.6 | 0.4 | 0.3 | 0.4 | 0.7 | 1.2 |
| 0.6 | 0.7 | 0.5 | 0.4 | 0.3 | 0.4 | 0.5 | 0.7 | 1.1 | 0.5 | 0.3 | 0.2 | 0.3 | 0.6 | 0.7 | 0.5 |
| 0.5 | 0.5 | 0.4 | 0.3 | 0.2 | 0.3 | 0.5 | 0.8 | 0.5 | 0.6 | 0.5 | 0.3 | 0.4 | 0.5 | 0.7 | 1.0 |
| 0.6 | 0.6 | 0.3 | 0.4 | 0.3 | 0.7 | 0.8 | 0.9 | 0.6 | 0.6 | 0.4 | 0.5 | 0.3 | 0.3 | 0.5 | 0.2 |
| 0.6 | 0.7 | 0.2 | 0.3 | 0.5 | 0.4 | 0.7 | 0.6 | 0.4 | 0.5 | 0.3 | 0.5 | 0.4 | 0.5 | 0.4 | 0.8 |

| | | | | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 0.6 | 0.6 | 0.3 | 0.5 | 0.3 | 0.5 | 0.6 | 0.5 | 0.7 | 0.3 | 0.5 | 0.5 | 0.3 | 0.5 | 0.6 | 0.7 |
| 0.4 | 1.0 | 0.7 | 0.5 | 0.4 | 0.4 | 0.5 | 0.6 | 0.7 | 0.3 | 0.4 | 0.5 | 0.2 | 0.5 | 1.0 | 1.4 |
| 0.5 | 0.7 | 0.4 | 0.6 | 0.5 | 0.4 | 0.7 | 0.6 | 0.5 | 0.5 | 0.4 | 0.3 | 0.3 | 0.4 | 0.9 | 1.2 |
| 0.9 | 0.7 | 0.5 | 0.3 | 0.3 | 0.3 | 0.7 | 0.4 | 0.4 | 0.5 | 0.6 | 0.3 | 0.4 | 0.4 | 0.8 | 1.1 |
| 0.4 | 0.6 | 0.3 | 0.4 | 0.3 | 0.3 | 0.6 | 0.3 | 0.5 | 0.5 | 0.4 | 0.3 | 0.4 | 0.4 | 0.4 | 0.6 |
| 0.4 | 0.6 | 0.5 | 0.4 | 0.3 | 0.4 | 0.5 | 0.6 | 0.7 | 0.4 | 0.3 | 0.4 | 0.2 | 0.7 | 0.5 | 0.5 |
| 0.6 | 0.9 | 0.4 | 0.3 | 0.2 | 0.4 | 0.7 | 0.3 | 0.4 | 0.3 | 0.5 | 0.3 | 0.4 | 0.5 | 0.7 | 0.6 |
| 0.4 | 1.0 | 0.3 | 0.4 | 0.2 | 0.5 | 0.6 | 0.5 | 0.6 | 0.6 | 0.4 | 0.3 | 0.4 | 0.7 | 0.3 | 0.6 |
| 0.5 | 0.5 | 0.5 | 0.3 | 0.3 | 0.4 | 0.4 | 0.3 | 0.5 | 0.4 | 0.3 | 0.3 | 0.4 | 0.9 | 1.0 | 1.1 |
| 0.5 | 0.5 | 0.5 | 0.3 | 0.2 | 0.5 | 0.5 | 0.5 | 0.0 | 0.4 | 0.5 | 0.3 | 0.3 | 0.8 | 0.7 | 0.9 |
| 0.4 | 0.6 | 0.2 | 0.3 | 0.3 | 0.6 | 0.7 | 0.5 | 0.5 | 0.4 | 0.4 | 0.4 | 0.5 | 0.7 | 1.0 | 1.2 |
| 0.4 | 0.9 | 0.3 | 0.4 | 0.3 | 0.6 | 0.3 | 0.4 | 0.3 | 0.5 | 0.5 | 0.5 | 0.4 | 0.4 | 0.8 | 0.9 |
| 0.5 | 0.5 | 0.3 | 0.5 | 0.3 | 0.6 | 0.6 | 0.6 | 0.3 | 0.5 | 0.3 | 0.3 | 0.6 | 0.5 | 1.2 | 0.5 |
| 0.4 | 0.7 | 0.3 | 0.2 | 0.2 | 0.7 | 0.5 | 0.5 | 0.2 | 0.4 | 0.3 | 0.6 | 0.3 | 0.4 | 0.7 | 1.1 |
| 0.5 | 0.7 | 0.7 | 0.3 | 0.6 | 0.5 | 0.9 | 0.5 | 0.5 | 0.3 | 0.3 | 0.5 | 0.5 | 0.7 | 1.1 | 0.6 |
| 0.4 | 0.3 | 0.5 | 0.4 | 0.5 | 0.5 | 0.7 | 0.5 | 0.4 | 0.5 | 0.4 | 0.4 | 0.4 | 0.4 | 0.7 | 0.7 |
| 0.5 | 1.0 | 0.5 | 0.6 | 0.3 | 0.6 | 0.6 | 0.7 | 0.3 | 0.6 | 0.3 | 0.3 | 0.5 | 0.6 | 0.6 | 0.6 |
| 0.6 | 0.7 | 0.4 | 0.5 | 0.2 | 0.7 | 0.5 | 0.6 | 0.4 | 0.3 | 0.4 | 0.4 | 0.5 | 0.7 | 0.7 | 0.8 |
| 0.6 | 0.9 | 1.3 | 0.5 | 0.5 | 0.5 | 0.5 | 0.3 | 0.4 | 0.5 | 0.3 | 0.3 | 0.3 | 0.6 | 0.3 | 0.8 |
| 0.5 | 0.5 | 1.0 | 0.4 | 0.6 | 0.5 | 0.4 | 0.6 | 0.3 | 0.4 | 0.7 | 0.2 | 0.4 | 0.4 | 0.3 | 0.4 |
| 0.3 | 0.6 | 0.8 | 0.3 | 0.4 | 0.5 | 0.5 | 0.8 | 0.3 | 0.4 | 0.3 | 0.5 | 0.5 | 0.5 | 0.2 | 0.2 |
| 0.5 | 0.9 | 0.8 | 0.4 | 0.3 | 0.5 | 0.8 | 0.5 | 0.4 | 0.3 | 0.4 | 0.4 | 0.3 | 0.7 | 0.2 | 0.6 |
| 0.5 | 0.8 | 0.7 | 0.4 | 0.6 | 0.5 | 0.7 | 0.4 | 0.5 | 0.3 | 0.4 | 0.2 | 0.5 | 0.6 | 0.6 | 0.6 |
| 0.5 | 0.7 | 0.8 | 0.3 | 0.4 | 0.5 | 0.5 | 0.4 | 0.4 | 0.4 | 0.4 | 0.3 | 0.8 | 0.6 | 2.0 | 1.6 |
| 0.5 | 0.7 | 0.8 | 0.2 | 0.9 | 0.7 | 0.9 | 1.3 | 0.8 | 1.5 | 1.0 | 1.0 | 0.7 | 0.3 | 2.3 | 1.3 |
| 0.5 | 0.9 | 0.8 | 0.5 | 0.6 | 0.7 | 0.6 | 2.6 | 1.5 | 1.4 | 0.9 | 1.2 | 0.5 | 0.5 | 1.6 | 1.7 |
| 0.3 | 0.2 | 0.7 | 0.5 | 0.6 | 0.8 | 0.5 | 3.9 | 0.9 | 1.8 | 1.7 | 0.9 | 0.4 | 0.3 | 0.8 | 1.3 |
| 0.6 | 0.1 | 0.5 | 0.6 | 0.5 | 1.2 | 1.3 | 0.7 | 1.8 | 2.1 | 1.1 | 0.3 | 0.9 | 0.3 | 2.6 | 1.1 |
| 0.5 | 0.5 | 0.8 | 0.4 | 0.8 | 1.2 | 0.9 | 2.3 | 1.7 | 2.7 | 1.3 | 0.6 | 0.3 | 0.3 | 1.1 | 1.7 |
| 0.2 | 0.4 | 0.7 | 0.6 | 0.7 | 1.2 | 0.5 | 0.8 | 0.2 | 1.6 | 1.1 | 1.0 | 1.0 | 0.3 | 0.5 | 0.5 |
| 0.2 | 0.4 | 1.1 | 0.5 | 1.0 | 0.8 | 1.2 | 1.2 | 0.2 | 1.9 | 1.4 | 0.9 | 1.1 | 0.3 | 0.9 | 0.6 |
| 0.3 | 0.7 | 1.1 | 0.4 | 1.3 | 0.9 | 0.6 | 3.1 | 0.7 | 0.9 | 1.0 | 0.5 | 1.0 | 0.2 | 0.6 | 1.1 |
| 0.3 | 1.0 | 0.9 | 0.4 | 1.1 | 0.9 | 0.3 | 1.0 | 0.8 | 1.2 | 1.3 | 0.4 | 1.0 | 0.3 | 0.8 | 1.0 |
| 0.5 | 1.0 | 0.6 | 0.3 | 1.6 | 1.0 | 0.7 | 1.2 | 1.9 | 0.8 | 0.9 | 1.0 | 1.2 | 0.3 | 0.3 | 0.4 |
| 0.3 | 1.0 | 0.5 | 0.5 | 0.7 | 0.3 | 1.1 | 1.5 | 0.8 | 0.7 | 1.0 | 0.6 | 0.4 | 1.1 | 0.6 | 0.9 |
| 0.2 | 1.7 | 0.7 | 0.5 | 1.0 | 1.0 | 1.6 | 1.1 | 0.8 | 0.3 | 0.9 | 0.6 | 0.4 | 1.1 | 1.4 | 0.9 |
| 0.4 | 1.0 | 1.1 | 0.4 | 0.7 | 0.7 | 0.5 | 1.0 | 1.1 | 0.4 | 0.4 | | | | | |

APPENDIX D

D.1. Matlab Codes For OM

D.1.1. For Normally Distributed Data

```
x0=normrnd(20,1,10000,1);
x=x0(1:500,1);
XT=[]
XT=x(1:500,1);
m=mean(XT)
s=std(XT)
ucl=m+2.57*s
lcl=m-2.57*s
m =

    20.0512
s =

    0.9889
ucl =

    22.5926
lcl =

    17.5097
plot(1:500,XT,'.');grid;hold on
plot(1:500,ones(1,500)*m,'.b',1:500,ones(1,500)*ucl,'.r',1:500,ones(1,500)*lcl,'.r');hold
off
axis([1 500 14 26])
```

01 MEAN SHIFT

```
XT1=[]
xt1=[]
XT1=x0(501:1000,1);
xt1=XT1+0.1;
plot(501:1000,xt1,'.');grid;hold on
plot(501:1000,ones(1,500)*m,'.b',501:1000,ones(1,500)*ucl,'.r',501:1000,ones(1,500)*l
cl,'.r');hold off
axis([501 1000 14 26])
```

025 MEAN SHIFT

```
XT2=[]
xt2=[]
XT2=x0(1001:1500,1);
xt2=XT2+0.25;
```

```

plot(1001:1500,xt2,'.');grid;hold on
plot(1001:1500,ones(1,500)*m,'.b',1001:1500,ones(1,500)*ucl,'.r',1001:1500,ones(1,500)*lcl,'.r');hold off
axis([1001 1500 14 26])

```

0.5 MEAN SHIFT

```

XT3=[]
xt3=[]
XT3=x0(1501:2000,1);
xt3=XT3+0.5;
plot(1501:2000,xt3,'.');grid;hold on
plot(1501:2000,ones(1,500)*m,'.b',1501:2000,ones(1,500)*ucl,'.r',1501:2000,ones(1,500)*lcl,'.r');hold off
axis([1501 2000 14 26])

```

1 MEAN SHIFT

```

XT4=[]
xt4=[]
XT4=x0(2001:2500,1);
xt4=XT4+1;
plot(2001:2500,xt4,'.');grid;hold on
plot(2001:2500,ones(1,500)*m,'.b',2001:2500,ones(1,500)*ucl,'.r',2001:2500,ones(1,500)*lcl,'.r');hold off
axis([2001 2500 14 26])

```

1.1 STD SHIFT

```

XST1=[]
XST1=normrnd(20,1.10,500,1);
plot(2501:3000,XST1,'.');grid;hold on
plot(2501:3000,ones(1,500)*m,'.b',2501:3000,ones(1,500)*ucl,'.r',2501:3000,ones(1,500)*lcl,'.r');hold off
axis([2501 3000 14 26])

```

1.25 STD SHIFT

```

XST2=[]
XST2=normrnd(20,1.25,500,1);
plot(3001:3500,XST2,'.');grid;hold on
plot(3001:3500,ones(1,500)*m,'.b',3001:3500,ones(1,500)*ucl,'.r',3001:3500,ones(1,500)*lcl,'.r');hold off
axis([3001 3500 14 26])

```

1.5 STD SHIFT

```

XST3=[]
XST3=normrnd(20,1.50,500,1);
plot(3501:4000,XST3,'.');grid;hold on

```

```
plot(3501:4000,ones(1,500)*m,'.b',3501:4000,ones(1,500)*ucl,'.r',3501:4000,ones(1,500)*lcl,'.r');hold off
axis([3501 4000 14 26])
```

2 STD SHIFT

```
XST4=[]
XST4=normrnd(20,2,500,1);
plot(4001:4500,XST4,'.');grid;hold on
plot(4001:4500,ones(1,500)*m,'.b',4001:4500,ones(1,500)*ucl,'.r',4001:4500,ones(1,500)*lcl,'.r');hold off
```

BACK TO NORMAL OPERATION

```
XT5=[]
XT5=normrnd(20,1,500,1);
plot(4501:5000,XT5,'.');grid;hold on
plot(4501:5000,ones(1,500)*m,'.b',4501:5000,ones(1,500)*ucl,'.r',4501:5000,ones(1,500)*lcl,'.r');hold off
axis([4501 5000 14 26])
```

D.1.2. For Non-normally Distributed Data

```
x0=chi2rnd(5,10000,1);
x=x0(1:1000,1);
XT=[]
XT=x(1:1000,1);
m=mean(XT)
s=std(XT)
ucl=m+2.57*s
lcl=m-2.57*s
m =
    4.8199
s =
    2.9079
ucl =
    12.2931
lcl =
   -2.6534
plot(1:1000,XT,'.');grid;hold on
plot(1:1000,ones(1,1000)*m,'.b',1:1000,ones(1,1000)*ucl,'.r',1:1000,ones(1,1000)*lcl,'.r');hold off
axis([1 1000 -10 30])
```

01 MEAN SHIFT

```
XT1=[]
xt1=[]
XT1=x0(1001:1500,1);
xt1=XT(501:1000,1)+0.1;
plot(1001:1500,xt1,'.');grid;hold on
plot(1001:1500,ones(1,500)*m,'.b',1001:1500,ones(1,500)*ucl,'.r',1001:1500,ones(1,500)*lcl,'.r');hold off
axis([1001 1500 -10 30])
```

025 MEAN SHIFT

```
XT2=[]
xt2=[]
XT2=x0(1501:2000,1);
xt2=XT2+0.25;
plot(1501:2000,xt2,'.');grid;hold on
plot(1501:2000,ones(1,500)*m,'.b',1501:2000,ones(1,500)*ucl,'.r',1501:2000,ones(1,500)*lcl,'.r');hold off
axis([1501 200 -10 30])
```

0.5 MEAN SHIFT

```
XT3=[]
xt3=[]
XT3=x0(2001:2500,1);
xt3=XT3+0.5;
plot(2001:2500,xt3,'.');grid;hold on
plot(2001:2500,ones(1,500)*m,'.b',2001:2500,ones(1,500)*ucl,'.r',2001:2500,ones(1,500)*lcl,'.r');hold off
axis([2001 2500 -10 30])
```

1 MEAN SHIFT

```
XT4=[]
xt4=[]
XT4=x0(2501:3000,1);
xt4=XT4+1;
plot(2501:3000,xt4,'.');grid;hold on
plot(2501:3000,ones(1,500)*m,'.b',2501:3000,ones(1,500)*ucl,'.r',2501:3000,ones(1,500)*lcl,'.r');hold off
axis([2501 3000 -10 30])
```

1.1 STD SHIFT

```
XST1=[]
XST1=normrnd(20,1.10,500,1);
plot(2501:3000,XST1,'.');grid;hold on
```

```
plot(2501:3000,ones(1,500)*m,'.b',2501:3000,ones(1,500)*ucl,'.r',2501:3000,ones(1,500)*lcl,'.r');hold off
axis([2501 3000 14 26])
```

1.25 STD SHIFT

```
XST2=[]
XST2=normrnd(20,1.25,500,1);
plot(3001:3500,XST2,'.');grid;hold on
plot(3001:3500,ones(1,500)*m,'.b',3001:3500,ones(1,500)*ucl,'.r',3001:3500,ones(1,500)*lcl,'.r');hold off
axis([3001 3500 14 26])
```

1.5 STD SHIFT

```
XST3=[]
XST3=normrnd(20,1.50,500,1);
plot(3501:4000,XST3,'.');grid;hold on
plot(3501:4000,ones(1,500)*m,'.b',3501:4000,ones(1,500)*ucl,'.r',3501:4000,ones(1,500)*lcl,'.r');hold off
axis([3501 4000 14 26])
```

2 STD SHIFT

```
XST4=[]
XST4=normrnd(20,2,500,1);
plot(4001:4500,XST4,'.');grid;hold on
plot(4001:4500,ones(1,500)*m,'.b',4001:4500,ones(1,500)*ucl,'.r',4001:4500,ones(1,500)*lcl,'.r');hold off
```

BACK TO NORMAL OPERATION

```
XT5=[]
XT5=normrnd(20,1,500,1);
plot(4501:5000,XT5,'.');grid;hold on
plot(4501:5000,ones(1,500)*m,'.b',4501:5000,ones(1,500)*ucl,'.r',4501:5000,ones(1,500)*lcl,'.r');hold off
axis([4501 5000 14 26])
```

D.1.3. For Industrial Data

```
XT=[]
XT=x(1:950,1);
hist(XT)
normplot(XT)
m=mean(XT)
s=std(XT)
ucl=m+2.57*s
lcl=m-2.57*s
```

```

m =
    0.4709
s =
    0.1660
ucl =
    0.8975
lcl =
    0.0444
plot(1:950,XT,');grid;hold on
plot(1:950,ones(1,950)*m,'b',1:950,ones(1,950)*ucl,'r',1:950,ones(1,950)*lcl,'r');hold
off
axis([1 950 -0.2 1.5])

XT1=[]
XT1=x(951:1179,1);
plot(951:1179,XT1,');grid;hold on
plot(951:1179,ones(1,229)*m,'b',951:1179,ones(1,229)*ucl,'r',951:1179,ones(1,229)*l
cl,'r');hold off
axis([951 1179 -0.3 4])

```

D.2. Matlab Codes For NM

D.2.1. For Normally Distributed Data

```

x0=normrnd(20,1,10000,1);
x=x0(1:1000,1);
[F2,xi2]=ksdensity(x,'npoints',5000,'width',0.075);
K2=[];
for i=1:1000
    [d,id]=min(abs(x(i)-xi2));
    K2(i,1)=F2(id);
end
y=normpdf(x,20,1);
plot(x,y,'g',xi2,F2,'b');grid
>> E0=[];
E0=y-K2;
m=mean(E0)
s=std(E0)
ucl=m+2.57*s
lcl=m-2.57*s
m =
    -0.0107
s =

```

```

    0.0276
ucl =
    0.0603
lcl =

-0.0817
figure(2);plot(1:1000,E0,'.');grid;hold on
>> figure(3);plot(1:1000,E0,'.');grid;hold on
plot(ones(1,1000)*m,('.b'))
plot(ones(1,1000)*ucl,('.g'))
plot(ones(1,1000)*lcl,('.g'))
axis([1 1000 -0.3 0.3])

```

01 MEAN SHIFT

```

XT=[]
xt1=[]
XT=x0(1001:1500,1);
xt1=XT+0.1;
ET=[];
zt=[];
for j=1:500
zt=[x((j+500):1000);xt1(1:j)];
[FZ,xiZ]=ksdensity(zt,'npoints',5000,'width',0.075);
Kt=[];
for i=1:500
[d,id]=min(abs(zt(i)-xiZ));
Kt(i,1)=FZ(id);
end
%yt=normpdf(zt(j),20,1);
yt=normpdf(xt1(j),20,1);
ET(j,1)=yt-Kt(500);
end
figure(2);plot(1001:1500,ET,'.');grid;hold on
plot(1001:1500,ones(1,500)*m,'.b',1001:1500,ones(1,500)*ucl,'.r',1001:1500,ones(1,500)*lcl,'.r')
axis([1001 1500 -0.50 0.50])

```

025 MEAN SHIFT

```

XT1=[]
xt2=[]
XT1=x0(1501:2000,1);
xt2=XT1+0.25;
ET1=[];
zt1=[];
for j=1:500
zt1=[x((j+500):1000);xt2(1:j)];
[FZ1,xiZ1]=ksdensity(zt1,'npoints',5000,'width',0.075);

```

```

Kt1=[];
for i=1:500
    [d,id]=min(abs(zt1(i)-xiZ1));
    Kt1(i,1)=FZ1(id);
end
%yt=normpdf(zt(j),20,1);
yt1=normpdf(xt2(j),20,1);
ET1(j,1)=yt1-Kt1(500);
end
figure(2);plot(1501:2000,ET1,'.');grid;hold on
plot(1501:2000,ones(1,500)*m,'.b',1501:2000,ones(1,500)*ucl,'.r',1501:2000,ones(1,500)*lcl,'.r')
axis([1501 2000 -0.50 0.50])

```

0.5 MEAN SHIFT

```

XT2=[]
xt3=[]
XT2=x0(2001:2500,1);
xt3=XT2+0.5;
ET2=[];
zt2=[];
for j=1:500
    zt2=[x((j+500):1000);xt3(1:j)];
    [FZ2,xiZ2]=ksdensity(zt2,'npoints',5000,'width',0.075);
    Kt2=[];
    for i=1:500
        [d,id]=min(abs(zt2(i)-xiZ2));
        Kt2(i,1)=FZ2(id);
    end
    %yt=normpdf(zt(j),20,1);
    yt2=normpdf(xt3(j),20,1);
    ET2(j,1)=yt2-Kt2(500);
end
figure(2);plot(2001:2500,ET2,'.');grid;hold on
plot(2001:2500,ones(1,500)*m,'.b',2001:2500,ones(1,500)*ucl,'.r',2001:2500,ones(1,500)*lcl,'.r')
axis([2001 2500 -0.50 0.50])

```

1 MEAN SHIFT

```

XT3=[]
xt4=[]
XT3=x0(2501:3000,1);
xt4=XT3+1;
ET3=[];
zt3=[];
for j=1:500
    zt3=[x((j+500):1000);xt4(1:j)];
    [FZ3,xiZ3]=ksdensity(zt3,'npoints',5000,'width',0.075);

```



```

Kt3=[];
for i=1:500
[d,id]=min(abs(zt3(i)-xiZ3));
Kt3(i,1)=FZ3(id);
end
%yt=normpdf(zt(j),20,1);
yt3=normpdf(xt4(j),20,1);
ET3(j,1)=yt3-Kt3(500);
end
figure(2);plot(2501:3000,ET3,'.');grid;hold on
plot(2501:3000,ones(1,500)*m,'.b',2501:3000,ones(1,500)*ucl,'.r',2501:3000,ones(1,500)*lcl,'.r')
axis([2501 3000 -0.50 0.50])

```

1.1 STD SHIFT

```

XT4=[]
XT4=normrnd(20,1.1,500,1);
ET4=[];
zt4=[];
for j=1:500
zt4=[x((j+500):1000);XT4(1:j)];
[FZ4,xiZ4]=ksdensity(zt4,'npoints',5000,'width',0.075);
Kt4=[];
for i=1:500
[d,id]=min(abs(zt4(i)-xiZ4));
Kt4(i,1)=FZ4(id);
end
%yt=normpdf(zt(j),20,1);
yt4=normpdf(XT4(j),20,1);
ET4(j,1)=yt4-Kt4(500);
end
plot(3001:3500,ET4,'.');grid;hold on
figure(2);plot(3001:3500,ET4,'.');grid;hold on
plot(3001:3500,ones(1,500)*m,'.b',3001:3500,ones(1,500)*ucl,'.r',3001:3500,ones(1,500)*lcl,'.r')
axis([3001 3500 -0.50 0.50])

```

1.25 STD SHIFT

```

XT5=[]
XT5=normrnd(20,1.25,500,1);
ET5=[];
zt5=[];
for j=1:500
zt5=[x((j+500):1000);XT5(1:j)];
[FZ5,xiZ5]=ksdensity(zt5,'npoints',5000,'width',0.075);
Kt5=[];

for i=1:500

```

```

[d,id]=min(abs(zt5(i)-xiZ5));
Kt5(i,1)=FZ5(id);
end
%yt=normpdf(zt(j),20,1);
yt5=normpdf(XT5(j),20,1);
ET5(j,1)=yt5-Kt5(500);
end
figure(2);plot(3501:4000,ET5,'.');grid;hold on
plot(3501:4000,ones(1,500)*m,'.b',3501:4000,ones(1,500)*ucl,'.r',3501:4000,ones(1,500)*lcl,'.r')
axis([3501 4000 -0.50 0.50])

```

1.5 STD SHIFT

```

XT6=[]
XT6=normrnd(20,1.5,500,1);
ET6=[];
zt6=[];
for j=1:500
zt6=[x((j+500):1000);XT6(1:j)];
[FZ6,xiZ6]=ksdensity(zt6,'npoints',5000,'width',0.075);
Kt6=[];
for i=1:500
[d,id]=min(abs(zt6(i)-xiZ6));
Kt6(i,1)=FZ6(id);
end
%yt=normpdf(zt(j),20,1);
yt6=normpdf(XT6(j),20,1);
ET6(j,1)=yt6-Kt6(500);
end
figure(2);plot(4001:4500,ET6,'.');grid;hold on
plot(4001:4500,ones(1,500)*m,'.b',4001:4500,ones(1,500)*ucl,'.r',4001:4500,ones(1,500)*lcl,'.r')
axis([4001 4500 -0.50 0.50])

```

2 STD SHIFT

```

XT7=[]
XT7=normrnd(20,2,500,1);
ET7=[];
zt7=[];
for j=1:500
zt7=[x((j+500):1000);XT7(1:j)];
[FZ7,xiZ7]=ksdensity(zt7,'npoints',5000,'width',0.075);
Kt7=[];
for i=1:500
[d,id]=min(abs(zt7(i)-xiZ7));
Kt7(i,1)=FZ7(id);
end
%yt=normpdf(zt(j),20,1);

```

```

yt7=normpdf(XT7(j),20,1);
ET7(j,1)=yt7-Kt7(500);
end
figure(2);plot(4501:5000,ET7,'.');grid;hold on
plot(4501:5000,ones(1,500)*m,'.b',4501:5000,ones(1,500)*ucl,'.r',4501:5000,ones(1,500)*lcl,'.r')
axis([4501 5000 -0.50 0.50])

```

BACK TO NORMAL OPERATION

```

X8=[]
X8=normrnd(20,1,1000,1);
E8=[];
[F8,xi8]=ksdensity(X8,'npoints',5000,'width',0.075);
K8=[];
for i=1:1000
[d,id]=min(abs(X8(i)-xi8));
K8(i,1)=F8(id);
end
y8=normpdf(X8,20,1);
plot(X8,y8,'g.',xi8,F8,'b.');
```

>> E8=[];

```

E8=y8-K8;
figure(2);plot(5001:6000,E8,'.');
```

>> grid;hold on

```

plot(5001:6000,ones(1,1000)*m,'.b',5001:6000,ones(1,1000)*ucl,'.r',5001:6000,ones(1,1000)*lcl,'.r')
axis([5001 6000 -0.30 0.30])

```

D.2.2. For Non-normally Distributed Data

```

x0=chi2rnd(5,10000,1);
x=x0(1:1000,1);
[F2,xi2]=ksdensity(x,'npoints',5000,'width',0.075);
K2=[];
for i=1:1000
[d,id]=min(abs(x(i)-xi2));
K2(i,1)=F2(id);
end
y=chi2pdf(x,5);
plot(x,y,'g.',xi2,F2,'b.');
```

>> grid

```

E0=[];
E0=y-K2;
figure(2);plot(1:1000,E0,'.');
```

>> figure(3);plot(1:1000,E0,'.');

```

grid;hold on
m=mean(E0)
s=std(E0)
ucl=m+2.57*s
lcl=m-2.57*s

```

```

plot(ones(1,1000)*m,('.b'))
plot(ones(1,1000)*ucl,('.g'))
plot(ones(1,1000)*lcl,('.g'))
axis([1 1000 -0.1 0.1])
m =

```

```

-0.0064
s =

```

```

0.0169
ucl =

```

```

0.0370
lcl =

```

```

-0.0499

```

01 MEAN SHIFT

```

XT=[]
xt1=[]
XT=x0(1001:1500,1);
xt1=XT+0.1;
ET=[];
zt=[];
for j=1:500
zt=[x((j+500):1000);xt1(1:j)];
[FZ,xiZ]=ksdensity(zt,'npoints',5000,'width',0.075);
Kt=[];
for i=1:500
[d,id]=min(abs(zt(i)-xiZ));
Kt(i,1)=FZ(id);
end
%yt=chi2pdf(zt(j),10);
yt=chi2pdf(xt1(j),5);
ET(j,1)=yt-Kt(500);
end
plot(1001:1500,ET,');grid;hold on
plot(1001:1500,ones(1,500)*m,'.b',1001:1500,ones(1,500)*ucl,'.r',1001:1500,ones(1,500)*lcl,'.r')
axis([1001 1500 -0.3 0.3])

```

025 MEAN SHIFT

```

XT1=[]
xt2=[]
XT1=x0(1501:2000,1);
xt2=XT1+0.25;
ET1=[];
zt1=[];

```

```

for j=1:500
zt1=[x((j+500):1000);xt2(1:j)];
[FZ1,xiZ1]=ksdensity(zt1,'npoints',5000,'width',0.075);
Kt1=[];
for i=1:500
[d,id]=min(abs(zt1(i)-xiZ1));
Kt1(i,1)=FZ1(id);
end
%yt=chi2pdf(zt(j),10);
yt1=chi2pdf(xt2(j),5);
ET1(j,1)=yt1-Kt1(500);
end
plot(1501:2000,ET1,');grid;hold on
plot(1501:2000,ones(1,500)*m,'.b',1501:2000,ones(1,500)*ucl,'.r',1501:2000,ones(1,500)*lcl,'.r')
axis([1501 2000 -0.3 0.3])

```

0.5 MEAN SHIFT

```

XT2=[]
xt3=[]
XT2=x0(2001:2500,1);
xt3=XT2+0.5;
ET2=[];
zt2=[];
for j=1:500
zt2=[x((j+500):1000);xt3(1:j)];
[FZ2,xiZ2]=ksdensity(zt2,'npoints',5000,'width',0.075);
Kt2=[];
for i=1:500
[d,id]=min(abs(zt2(i)-xiZ2));
Kt2(i,1)=FZ2(id);
end
%yt=chi2pdf(zt(j),10);
yt2=chi2pdf(xt3(j),5);
ET2(j,1)=yt2-Kt2(500);
end
plot(2001:2500,ET2,');grid;hold on
plot(2001:2500,ones(1,500)*m,'.b',2001:2500,ones(1,500)*ucl,'.r',2001:2500,ones(1,500)*lcl,'.r')
axis([2001 2500 -0.3 0.3])

```

1 MEAN SHIFT

```

XT3=[]
xt4=[]
XT3=x0(2501:3000,1);
xt4=XT3+1;
ET3=[];
zt3=[];

```

```

for j=1:500
zt3=[x((j+500):1000);xt4(1:j)];
[FZ3,xiZ3]=ksdensity(zt3,'npoints',5000,'width',0.075);
Kt3=[];
for i=1:500
[d,id]=min(abs(zt3(i)-xiZ3));
Kt3(i,1)=FZ3(id);
end
%yt=normpdf(zt(j),20,1);
yt3=chi2pdf(xt4(j),5);
ET3(j,1)=yt3-Kt3(500);
end
plot(2501:3000,ET3,'.');grid;hold on
figure(2);plot(2501:3000,ET3,'.');grid;hold on
plot(2501:3000,ones(1,500)*m,'.b',2501:3000,ones(1,500)*ucl,'.r',2501:3000,ones(1,500)*lcl,'.r')
axis([2501 3000 -0.3 0.3])

```

BACK TO NORMAL OPERATION

```

x0=chi2rnd(5,10000,1);
xS=x0(3001:4000,1);
[FS,xiS]=ksdensity(xS,'npoints',5000,'width',0.075);
KS=[];
for i=1:1000
[d,id]=min(abs(xS(i)-xiS));
KS(i,1)=FS(id);
end
yS=chi2pdf(xS,5);
plot(xS,yS,'g',xiS,FS,'b');grid
ES=[];
ES=yS-KS;
m=mean(ES)
s=std(ES)
ucl=m+2.57*s
lcl=m-2.57*s
plot(3001:4000,ES,'.');grid;hold on
plot(3001:4000,ones(1,1000)*m,'.b',3001:4000,ones(1,1000)*ucl,'.r',3001:4000,ones(1,1000)*lcl,'.r')
axis([3001 4000 -0.1 0.1])

```

D.2.3. For Industrial Data

```

xt=x(1:950);
normplot(xt)
[F2,xi2]=ksdensity(xt,'npoints',5000,'width',0.05,'kernel','normal');
figure(1);y2=normpdf(xt,0.4741,0.1674);
plot(xi2,F2,'b',xt,y2,'g');grid

```

```

K2=[];
for i=1:950
    [d,id]=min(abs(xt(i)-xi2));
    K2(i,1)=F2(id);
end
E0=[];
E0=y2-K2;
m=mean(E0)
s=std(E0)
ucl=m+2.57*s
lcl=m-2.57*s
m =
    -0.0674
s =

    0.2198
ucl =

    0.4976
lcl =

    -0.6324
figure(3);plot(1:950,E0,'.');grid;hold on
plot(ones(1,950)*m,('b'))
plot(ones(1,950)*ucl,('g'))
plot(ones(1,950)*lcl,('g'))

XT=[]
XT=x(950:1179,1);
ET=[];
zt=[];
for j=1:230
    zt=[x((j+1):230);XT(1:j)];
    [FZ,xiZ]=ksdensity(zt,'npoints',5000,'width',0.05,'kernel','normal');
    Kt=[];
    for i=1:230
        [d,id]=min(abs(zt(i)-xiZ));
        Kt(i,1)=FZ(id);
    end
    yt=normpdf(XT(j),0.4741,0.1674);
    ET(j,1)=yt-Kt(230);
end
plot(950:1179,ET,'.');grid;hold on
plot(950:1179,ones(1,230)*m,'.b',950:1179,ones(1,230)*ucl,'.r',950:1179,ones(1,230)*lcl,'.r')

```